TE 3.33 - Environmentally Controlled Facilities

209E Class	ISO Class	Shop	Facility	Building
100	5	6.2.94101	Instruments Shop (Precision Instrument Bearing Rework), Laminar Flow Work Stations	137
100	5	6.3.657	Hydraulic Fluid Sampling, Laminar Flow Work Stations	137
10,000	7	6.2.96331	Hydraulic Pumps, Propeller Housings, and Electric Servos Repair, Clean Room	133
10,000	7	6.2.96334	Hydraulic Actuators, Wenches, and Reservoirs Repair, Clean Room	133
10,000	7	6.2.96335	Fuel Controls Repair, Clean Room	133
10,000	7	6.2.96454	Bearing Shop (Gauging and Dimensioning Area), Clean Room	133
100,000	8	6.2.94101	Instruments Shop (Guidance and Stabilization Systems Rework), Laminar Flow Work Stations	137
100,000	8	6.2.94205	ATE/Avionics Repair Shop, Laminar Flow Work Stations	188
100,000	8	6.2.96454	Bearing Shop (Preservation and Packaging Area), Clean Room	133
300,000	9	6.2.94203	Industrial Instrumentation and Physical Measurement Shop (Master Gauge Room), Clean Room	137
300,000	9	6.9.1	Precision Measurement Cell, (Naval Engine Airfoil Center)	4225

TE 3.33 - Environmentally Controlled Facilities

TE 3.34 – Industrial Compound Freezer Repair Work Orders

Government provides data on historical workload in this technical exhibit. This data is raw and represents actual communication among customers, maintenance planners, and artisans. The data is as it appears in the maintenance management system except for removal of personal information, inappropriate language, and acronyms expanded as practicable. Each set of data includes a ticket number, ticket date, and a problem description. The tickets approximate the work required during the base one-year period.

The work orders numbers in this technical exhibit may not match exactly the workload forecast in Section C-7. There are two reasons. First, customers occasionally submit more than one requirement for a single problem indicating the recorded workload over represents the work performed. Second, artisans perform a substantial fraction of their work on verbal orders or on their own initiative indicating the recorded workload under represents work performed. However, the net result approximates actual work required.

We audited by sampling the workload in each technical exhibit. We also sought subject matter expert advice on the amount of over- and under-reporting in each area. The result is our estimate of the amount of over- and under-reporting of each workload set. Thus, to get the forecast values in C-7 for the workload in this Technical Exhibit, we increased the number of tickets by 20 percent to adjust for under reported tickets.

Ticket Number	Date	Description
91630	10/24/00	Reinstall freezer panels and insulation on the upright freezer behind bldg 1006. I will send to DRMO and task an order form a replacement. Thanks.
92057	10/30/00	Freezer that was delivered on 10/27/00 has not reached desired temp of -100 degrees F. Temp today @0700 was –86 degrees. There is no product stored, therefore no reason to open door. Please expedite repair.
93940	11/20/00	Chest freezer in mixing room not maintaining -44 it is staying at -33 this is a work stoppage
93955	11/20/00	Chest freezer in mixing room is not maintaining -48 this is a work stoppage, it went down Friday Nov 17-2000.
94404	11/27/00	Freezer not working will send to building 1006. Thanks
95999	12/13/00	Freezer in Canopy shop is cycling on and off continuously.
96210	12/15/00	Freezer in canopy shop is cycling on and off continuously.
99078	01/22/01	Walk-in freezer is up to 20 degrees. Should be zero.
101099	02/10/01	Freezer keeps cycling over and over had to unplug to keep from over heating. This is the second ticket on this problem. Please repair ASAP.
101332	02/13/01	Freezer is not working need help ASAP loosing parts.
101647	02/15/01	So-Low w freezer in heat treat area has temp rising- need service ASAP will cause work stoppage in heat treat area soon

Technical Exhibit 3.34, Page 1 of 2 Revised: 04/03/03, 10:59 AM

Ticket Number	Date	Description
103019	03/05/01	Freezer had defrosted motor don't sound like it's running work stoppage.
103676	03/12/01	Freezer will not maintain temperature.
104311	03/19/01	Chest freezer that needs to be at -48 is at -18 and is not going down.
104361	03/19/01	Huge freezer down won't come up. Work stoppage
104595	03/21/01	Freezer in canopy shop is inoperable was repaired recently, but when turned on it never got cold and the motor kept recycling.
104744	03/22/01	Freezer in canopy shop is inoperable. Was repaired recently, but when turned off it never got cold and the motor kept recycling.
105174	03/28/01	Check freezer to make sure temp is working correctly freezer is located next to wotan along wall
107886	04/30/01	Walk in freezer down
109244	05/15/01	Freezer not working again.
110003	05/23/01	Freezer is not working. This is the 3rd ticket input on this freezer since 11/00 (ref ticket numbers 93909 and 104311). Last ticket was closed and the freezer was never fixed. If this unit is ber please advise so we can fund to have it replaced.
111947	06/14/01	So-Low freezer will not go back to proper temp. Since power outage Sunday.
112854	06/26/01	Freezer needs an alarm and a different plug. The EIN would not take in the system-65923030757
113490	07/05/01	Deep freezer is to warm, work stoppage
113637	07/06/01	Freezer is down in 4224 HDSC. Freezer needs to be repaired ASAP. Work stoppage.
114953	07/24/01	Ink pen for freezer chart needs to be changed ASAP. Part # for ink pen is 605 004 02. Omega engineering
115287	07/26/01	Work stoppage! Freezer temperature will not maintain set temp. Should be - 90-100% it goes down as low as -1%. This freezer is used to store potting.
116118	08/06/01	Hazardous materials freezer is slowing rising in temperature and will affect materials inside. This will affect a work stoppage condition in support of the production line. Freezer is located in sse cage in AV-8 harrier hanger area just right of door
116674	08/13/01	Repair walk in freezer
117267	08/20/01	This freezer was down when we came in today I don't know when it went out. This is the only chest freezer we have for film. (work stoppage).
117582	08/22/01	This freezer is staying at -67 and we need it to be -90 or better before we can use it for potting.
118177	08/29/01	Freezer: freezer in mixing room, bldg 137, check temperature reading, showing –60 F, to maintain –100 F.
118181	08/29/01	Freezer: check freezer in mixing room, bldg 137, check temperature, showing –60 F, to maintain –100 F.
118188	08/29/01	Freezer: check freezer in mixing room, bldg 137, freezer showing –75 F, to maintain –100 F.
119951	09/21/01	Freezer in canopy shop isn't working properly. Temperature is reading 40 degrees; it is set at -60 degrees. Please repair ASAP.
120139	09/24/01	So-low freezer will not maintain -100 at the present time; it is -61. On Friday 9/21 the freezer was at +5 which is unacceptable for the sealants.

TE 3.33 – Industrial Compound Freezer Repair Work Orders

TE 3.35 – Cooling Tower Work Order

Government provides data on historical workload in this technical exhibit. This data is raw and represents actual communication among customers, maintenance planners, and artisans. The data is as it appears in the maintenance management system except for removal of personal information, inappropriate language, and acronyms expanded as practicable. Each set of data includes a ticket number, ticket date, and a problem description. The tickets approximate the work required during the base one-year period.

The work orders numbers in this technical exhibit may not match exactly the workload forecast in Section C-7. There are two reasons. First, customers occasionally submit more than one requirement for a single problem indicating the recorded workload over represents the work performed. Second, artisans perform a substantial fraction of their work on verbal orders or on their own initiative indicating the recorded workload under represents work performed. However, the net result approximates actual work required.

We audited by sampling the workload in each technical exhibit. We also sought subject matter expert advice on the amount of over- and under-reporting in each area. The result is our estimate of the amount of over- and under-reporting of each workload set. Thus, to get the forecast values in C-7 for the workload in this Technical Exhibit, we increased the number of tickets by 20 percent to adjust for under reported tickets.

Ticket No	Date Created	Description
91972	10/27/00	Please have the engine test cell cooling tower (located above TC3) cleaned. Also, clean the cold sump located below the tower, inside the bldg.
92985	11/07/00	Cooling tower leaking
95989	12/13/00	Replace belts on the 383 ton cooling tower; do not shut system down without prior approval.
96342	12/18/00	Dyno H2O in fluctuating shut down engine run. Work stoppage
96376	12/18/00	Main water valve which feeds cooling water to pumps on ivadizer (IVD) in bldg 133 next to soda machines is leaking when in the open position. POC in the plating shop bldg 4035.
96380	12/18/00	Please fix water leak in test cell
96440	12/19/00	Main water valve which feeds cooling water to pumps on ivadizer (IVD) in bldg 133 next to soda machines is leaking when in the open position. POC in the plating shop
96822	12/22/00	Dyno out temp spiked @220 +degrees as engine went up on power. Dyno water temp in climbed to 125 deg at same time. Unable to go above 85% ng, dyno water temps spike and shut down engine.
97435	01/04/01	Repair bleed offline to cooling tower on the plating shop
97436	01/04/01	Install controller on the autoclave cooling in bldg 4224
97711	01/06/01	Please unstop drain on T-58 water tower.
97800	01/08/01	Please unstop drain on T-58 water tower.

Technical Exhibit 3.35, Page 1 of 2 Revised: 11/06/02, 10:39 AM

Ticket No	Date Created	Description
98211	01/11/01	Need electrical troubleshooting on T58 test cell #3 cooling tower fan system. Has been working on this issue.
98841	01/18/01	Engineering requires maintenance help today to test maximum flow capacity of cooling tower and closed loop cooling system.
99378	01/24/01	Need coolant in T58 manual test stand #1 / work stop
100177	02/01/01	Replace belts on the 383 ton cooling tower; do not shut system down without prior approval.
100178	02/01/01	Procure controller for chemical feed on autoclave in bldg 4224.
100229	02/01/01	Dyno water pressure dropped to below operating limits. It registered in limit prior to starting engine but gradually dropped off to below operating limits. Work stoppage
101928	02/21/01	Attn: check cooling tower floats in bldg 4224 and 4225. Contact before fixing
101940	02/21/01	Repair clean tower as per instructions
104848	03/23/01	Cooling tower needs cleaning prior to operation work stoppage
104940	03/26/01	1. Relocate the clamp-on panametrics water meter from bldg 137 pneumatics to bldg 139 to measure the amount of cooling water flowing through the compressors. 2. Connect to cooling tower.
104968	03/26/01	Repair as necessary the solenoid valve on cooling tower 4224-OL1
104971	03/26/01	Provide an estimate to install 2 pumps, controller, control panel, hose, piping, solenoid valve, and electric power to 133-HCL 2
106253	04/09/01	Chill water tank over flowing.
106504	04/12/01	H2O over temp alarm.
108139	05/02/01	Adjust float in cooling tower as per instructions
109313	05/15/01	Assist engineering in developing discrepancy lists for new plant air compressor cooling tower installations at bldg 133 and bldg 139.
111680	06/12/01	Replace chemical controller on cooling tower # OL3.
112233	06/18/01	Cooling tower in-op, switch in on position but fans not working
112577	06/22/01	Heat treat cooling tower fan is not cycling on and off when in auto mode. Fan just stays off while in auto
114343	07/17/01	Leak on the cooling tower out back from a pressurized source
116047	08/06/01	Nose test cell running hot. Work stoppage
117289	08/20/01	Please change coolant in this sip jig grinder.
117525	08/21/01	Not getting water from chiller. Over temperature.
117650	08/22/01	The chilled water loop in shop 93563 is not flowing or is clogged, causing the jet edge water knife to overheat. This is causing a work stoppage at the water knifethanks.
118466	08/31/01	No chilled water on T58 test stand
119714	09/19/01	Clean cooling tower as per instructions

TE 3.35 – Cooling Tower Work Orders

TE 3.36 - Woodwork and Carpentry Repair Work Orders

Government provides data on historical workload in this technical exhibit. This data is raw and represents actual communication among customers, maintenance planners, and artisans. The data is as it appears in the maintenance management system except for removal of personal information, inappropriate language, and acronyms expanded as practicable. Each set of data includes a ticket number, ticket date, and a problem description. The tickets approximate the work required during the base one-year period.

The work orders numbers in this technical exhibit may not match exactly the workload forecast in Section C-7. There are two reasons. First, customers occasionally submit more than one requirement for a single problem indicating the recorded workload over represents the work performed. Second, artisans perform a substantial fraction of their work on verbal orders or on their own initiative indicating the recorded workload under represents work performed. However, the net result approximates actual work required.

We audited by sampling the workload in each technical exhibit. We also sought subject matter expert advice on the amount of over- and under-reporting in each area. The result is our estimate of the amount of over- and under-reporting of each workload set. Thus, to get the forecast values in C-7 for the workload in this Technical Exhibit, we first decreased the number of tickets by 4.7 percent to adjust for over-reported requirements. The then increased the number of tickets by 20 percent to adjust for under reported tickets.

Ticket Number	Date	Description of Problem
89590	10/2/00	Install a 36" door in the existing 48" opening. Jam will need to be fired out and sheet rocked and remove all baseboards in new area
89594	10/2/00	Repair mule carts to return to service.
89597	10/2/00	Part of the floor inside the back of can 1379 is rotten. The forklift runs over this part of the floor and it is falling through.
89682	10/2/00	Need to replace the rubber pads on 20 ea aluminum workstands located in the GSE compound. These stands cannot be used until the pads are replaced.
89691	10/2/00	Modify cal lab tooling box as per instruction.
89695	10/2/00	Repair front entrance door by SRC card room. Someone can get hurt with the force use to open it. Safety factor. Thanks.
89722	10/3/00	Repair hole in wall and or ceiling of lobby in bldg 133, help keep fire from spreading
89759	10/3/00	Install braces on wood calibration equipment racks in warehouse area of building
89785	10/3/00	Request installation of door closure on Engine Program Office door, Bldg 133.
89789	10/3/00	Need lid and side put back on CH-53 Fuel Cell Box. The Box is at Bldg 83 Carpenter Shop.

Technical Exhibit 3.36, Page 1 of 30 Revised: 04/03/03, 11:01 AM

Ticket Number	Date	Description of Problem
89909	10/4/00	Repair hole in wall and or ceiling of lobby in bldg 133, help keep fire from spreading
90017	10/5/00	The automatic door closer on the door for the Men's head has came loose. Needs to be re-secured with bolts rather than metal screws.
90020	10/5/00	Install 7 ea door stops on door bottoms or hinges bldg 298, 2nd floor POC bldg 298
90033	10/5/00	Replace door closure on single passage door next to rollup door facing flight line (NADEP side only).
90075	10/6/00	Mount fire extinguisher to wall
90092	10/6/00	Repair old mule carts and modify as necessary to return to service.
90111	10/6/00	Modify wooden tool containers as per instruction.
90112	10/6/00	Modify wooden tool containers as per instruction. Calibration Lab.
90174	10/10/00	Please remount key locker on wall, as it came off.
90237	10/10/00	Door closer hangs up on door and it will not open. Please fix ASAP. Safety hazard.
90362	10/11/00	Door closer broken. Hangs up and will not let door open. Safety hazard. Second call.
90419	10/11/00	Wood door from hall to office will not open but 1/3 of the way. It drags on floor.
90471	10/12/00	Please reinstall the shop Key Box to the cinder wall, from where it came off. Thank you.
90501	10/12/00	Remove wall and dispose of material, header off wall and sheetrock, reattach ceiling grid.
90544	10/12/00	Automatic doorstop has come unfastened again.
90561	10/12/00	Provide minor carpentry repairs for Industrial Maintenance CA team.
90574	10/12/00	Replace damaged cased molding around recessed bookshelves. Install chair rail around walls in front part of office to protect walls from chair damage. Stain and seal to match existing décor. (send to mod squad)
90606	10/13/00	Install braces on wood calibration equipment racks in warehouse area of building
90611	10/13/00	Need to replace wood and rubber on 3 ea H53 blade dollies located in the GSE compound. 65923056698, 65923020753. Thank you and good morning
90623	10/13/00	Remove and dispose of old wood engine crates.
90625	10/13/00	Make repairs to mule carts.
90812	10/16/00	Repair coat rack per verbal instructions
90855	10/17/00	Move fire extinguisher from present location where it is in the way to another wall in same room. Paint as req'd
90866	10/17/00	Repair walls and patch holes. Replace all ceiling tile and fix baseboard. Paint to match.
90872	10/17/00	Replace ceiling tiles in ladies room front office bldg 137. Repair grid as required and do a first class job. See for coordination with closing the bathroom.
90879	10/17/00	Need to replace the wood and bumper pads (as necessary) on 21 ea CH46 wrap a round work stands located in the GSE compound behind bldg 188. These are large stands that are moved with a forklift.
91041	10/18/00	Install new table tops

Ticket Number	Date	Description of Problem
91054	10/18/00	Refurbish warehouse wagons some need woodwork, welding, and painting.
91056	10/18/00	Powerk the new mule was one with plintle health and to them as indicated as
91178	10/19/00	Modify existing platform in front of balancing machine Ein 007992, to have evenly spaced steps on it. The present steps do conform to safety requirements and present a safety hazard.
91420	10/23/00	Mezzanine G, louvered panel in bottom part of door needs to be re-installed
91474	10/23/00	Need to replace the rubber pads on 2 ea aluminum Workstands located at the carpenter shop.
91584	10/24/00	Manufacture and install light blocking device for doors in photo lab. See for details
91599	10/24/00	Repair damaged work bench top
91706	10/25/00	Need ASAP- replace damaged ceiling tile classroom 5 and 9 Repair wall, paint classroom 9
91788	10/26/00	Please cut notches in new dry ice containers as per instruction.
91814	10/26/00	Repair desk drawer. Won't stay in place.
91884	10/26/00	Replace wood and rubber as necessary on CH-46 fuselage cradle located at carpenter shop thank-you
91905	10/26/00	Please cut notches in new dry ice containers as per instruction.
91997	10/27/00	Modify transportation carts to avoid accidents.
92037	10/28/00	The door in the office sticks at the top and should be cut to fit properly. It is extremely hard to open.
92183	10/30/00	Take apart, move, and rebuild BIG green cabinet in Transverse Mezzanine to bldg 159, Receiving Deck. Also remove wall-mounted bookshelves in office and relocate.
92211	10/31/00	Take apart, move, and rebuild BIG green cabinet in Transverse Mezzanine to bldg 159, Receiving Deck. Also remove wall-mounted bookshelves in office and relocate.
92261	10/31/00	Need information board hung on wall.
92268	10/31/00	Need information board hung on wall.
92309	10/31/00	Need information board hung on wall.
92319	10/31/00	Cut material
92381	11/1/00	Replace plywood on trailer
92386	11/1/00	Repair wood floor
92387	11/1/00	Replace miter box used for F402 engine seal repair.
92432	11/1/00	Need to have 12 ea pieces of 3/4 inch plywood cut to 41" x 75". Call for pickup
92442	11/1/00	We need a vertical wall mailbox rack (wood) built for 8 mailboxes to fit on, for 6.2.944 new offices in their SBU.
92580	11/2/00	Install white board
92634	11/3/00	Cut material.
92667	11/3/00	Repair mule carts

Ticket Number	Date	Description of Problem
92669	11/3/00	Repair door per instruction
92673	11/3/00	Replace door with new door and jam.
92737	11/4/00	A-frame F located in the center of the hanger has a broken wheel that needs replacing.
92766	11/6/00	Repair a mule cart for use by shop 52320
92837	11/6/00	Bldg 133 Union Bulletin Board needs to be replaced. Existing bulletin board fell and broke when it hit the floor. POC for additional information Code 6.2.960 Division Secretary.
92864	11/7/00	Repair tabletop. Boards are separating and warping.
92876	11/7/00	Floor in clean room has a small area that needs to be patched.
92977	11/7/00	Need to replace the wood on an H53 floorboard dolly. Paint with non-skid.
92978	11/7/00	Need to replace wood on H53 floorboard as necessary. Paint with non-skid
93010	11/8/00	Need to replace the wood, padding, and paint H46 blade dolly. Dolly is located in the GSE compound. Thank you and good morning
93011	11/8/00	Need to replace the wood, padding, and paint H46 blade dolly. Dolly is located in the GSE compound.
93013	11/8/00	Need to replace the wood, padding, and paint a H46 blade dolly. Dolly is located in the GSE compound.
93014	11/8/00	Need to replace the wood, padding, and paint a H46 blade dolly. Dolly is located in the GSE compound.
93015	11/8/00	Need to replace the wood, padding, and paint a H53 blade dolly. Dolly is located in the GSE compound.
93018	11/8/00	Need to replace the wood and padding, on a H53 blade dolly. Dolly is located in the GSE compound.
93093	11/8/00	Modify tabletop.
93115	11/8/00	Remove wooden cabinet off wall in Security office and remount per customer's specifications. Remove and dispose of mirror and bookshelf.
93219	11/9/00	Replace three water damaged ceiling tiles in division Secretary office, mezzanine g, bldg 137
93225	11/9/00	Repair deteriorated roof and joists as per on site visit discussion
93258	11/9/00	Please remove bookcases from bldg 163 and install them in the 944 FDU office.
93292	11/11/00	Re-install wood block assy. And affix rubber molding
93410	11/13/00	Task 111513 - Install fire extinguisher in top enclosure in ASKARS Shop 21430. Item in can #1379.
93416	11/13/00	Desk needs to be level
93443	11/13/00	Repair data stands as required, Screws missing in hinges, drawers broken, Plexiglas broken. H-46 Hangar
93460	11/14/00	Door to bottom area of learning lab TV is jamming.
93607	11/15/00	Shop 95448 had the carpentry shop make a total of 10 base plywood for our floorboards to sit in while being worked. The base on the bottom of the stands are coming apart on all 10 items made. Please send someone to look at and correct the problem.
93638	11/15/00	Desk needs to be leveled, drawers are opening on their own

Ticket Number	Date	Description of Problem
93722	11/16/00	Have a 4-slot paper holder made for break room to hold loose papers and pass on information.
93801	11/17/00	Need to have production shop board mounted
93845	11/17/00	Fix hinges on office door and adjust closer.
93846	11/17/00	Put automatic closer on door between p/c area and instrument area
93952	11/20/00	Need hinge repaired on door.
94138	11/21/00	Original weather stripping on both sets of main doors in lobby are either missing or in disrepair leaving at least a 1/4" gape. Request replacement that will function properly without interfering with locks.
94426	11/27/00	Need to have production shop board mounted
94427	11/27/00	Have a 4-slot paper holder made for break room to hold loose papers and pass on information.
94428	11/27/00	Desk needs to be leveled, drawers are opening on their own
94431	11/27/00	Repair data stands as required. Screws missing in hinges, drawers broken, Plexiglas broken. H-46 Hangar
94432	11/27/00	A-frame F located in the center of the hanger has a broken wheel that needs replacing.
94433	11/27/00	Replace plywood on trailer
94513	11/28/00	Need hinge repaired on door.
94635	11/29/00	A-frame F located in the center of the hanger has a broken wheel that needs replacing.
94636	11/29/00	Repair data stands as required. Screws missing in hinges, drawers broken, Plexiglas broken. H-46 Hangar
94641	11/29/00	1
94762	11/30/00	Need under table keyboard platform attached to deck. have the parts just need someone to attached them.
94770	11/30/00	Cut wood per instructions
94782	11/30/00	Doorway in Defense Printing Service Office - Door frame/jam is too high to push heavy carts over. Need to install incline to help prevent injuries.
94792	11/30/00	Exit door will not open due to new flooring
94829	11/30/00	pottom molding needs replaced. Thank You.
94831	11/30/00	Task 111905 - place devices in wall to accommodate hanging pictures per attached 4235/2
94902	12/1/00	Desk drawer broke. Need to have drawer cut to 16" in depth.
94954	12/1/00	Several sawhorses in the shop are in desperate need of repair. Refit and tighten 25 ea
95015	12/4/00	Need to replace the rubber pads on 11 ea aluminum Workstands located at the carpenter shop.
95050	12/4/00	Need to drill wooden blocks as per sample 4 ea
95156	12/5/00	Please relocate key locker to front of office in shop 96119. The key locker is currently on the side of office.
95214	12/5/00	Made awning and steps for existing door.

Ticket Number	Date	Description of Problem
95241	12/5/00	Install hasp on locker so it can be padlocked.
95275	12/6/00	Assemble and install storage shelves
95415	12/7/00	Modify cal lab tooling box as per instruction.
95479	12/7/00	Need steps modify to fit machine now.
95581	12/8/00	Urgent Request. Glue plywood patches to back side of floor tile in Mezzanine G computer room, bldg 137. Holes in floor are resulting in poor airflow to equipment. Contact for instructions.
95595	12/8/00	Replace damaged or missing ceiling tiles in hallway on the NE end of building 133 near elevator.
95598	12/8/00	Install hasp on locker so it can be padlocked.
95720	12/11/00	Storage drawer needs to be reinstalled.
95759	12/11/00	Need steps modify to fit machine now.
95760	12/11/00	Urgent Request. Glue plywood patches to back side of floor tile in Mezzanine G computer room, bldg 137. Holes in floor are resulting in poor airflow to equipment. Contact for instructions.
95774	12/11/00	A ceiling tile in shop needs replacing
95837	12/12/00	Need 3/4 plywood cut per specs.
95952	12/12/00	Repair or replace all damaged wood on H-46 wrap around stands. Stands located in the H-46 hangar and in storage yard.
96008	12/13/00	Install marker board in 940 sbu area for requestor
96076	12/14/00	Floor rotting need wood work
96077	12/14/00	Need door closure installed on can 1385.
96083	12/14/00	Mechanical room Bldg 133 remove wood workbench and screened in wall
96189	12/15/00	Repair mule carts as required. Carpentry and painting.
96191	12/15/00	Repair mule carts as necessary to return to service.
96216	12/15/00	Repair 3x5 section of drywall in ceiling of hooch, Receiving deck, B159. Send to Nelson Contracting. Thanks
96227	12/15/00	Patch the hole in the wall with plywood.
96229	12/15/00	Please remove yellow chairs in conference room, put them in classroom on second deck, replace with eighteen chairs on shop floor, and remove gray chairs from building. Thank you.
96248	12/15/00	Repair floorboards and deck boards.
96337	12/17/00	Didg 1798.
96406	12/18/00	Weather-stripping at the control room and maintenance room door allows wind driven rain. Repair/replace.
96407	12/18/00	
96408	12/18/00	Water damage is present to the 1X 4 wood trim above a mezzanine window. AIS INSPECTION
96413	12/18/00	Hinges are coming unattached to shop entrance doors.

Ticket Number	Date	Description of Problem
96487	12/19/00	Would like a doorstop to be installed on 6.3.61400 Supervisor's door and the Data Control Center's door. POC for additional information
96526	12/19/00	Please cut new Plexiglas diffusers for lights in paint booth
96530	12/20/00	Need to replace the rubber on 13 ea single prop stands located at the carpenter shop.
96538	12/20/00	Repair holes in wall to correct fire inspection.
96541	12/20/00	Cut off 3 doors to keep from dragging on new
96685	12/21/00	Change out all door casing and baseboard moldings. Paint inside door casing to match existing. Stain moldings to match.
96686	12/21/00	Need to have holes in wooden end caps drilled to fit F/E gear case. Refer to carpentry shop as per supervisor.
96695	12/21/00	Repair tool carts per instruction.
96697	12/21/00	Repair wood cans per instruction
96698	12/21/00	Repair carts with wood and paint new wood.
96741	12/21/00	The stairs wooden treads to the engine parts pool area mezzanine are worn which creates a safety hazard. Request these wooden treads be removed and a dust plate be installed behind these stairs.
96820	12/22/00	Hang bookshelves, put up partitions and anything else middle level, high rise Mezzanine, H-46 Hangar. Send to Coastal Waterproofing. Request do this ASAP after Christmas. Thanks!
96857	12/26/00	Repair door and replace closer.
96860	12/26/00	Door on office area off the hinges
96862	12/26/00	Modify tabletop.
96880	12/26/00	Fix doors in penthouse
96894	12/26/00	Back door to shop 96111 coming apart at door handle and closing device.
96976	12/27/00	Need one 8"x10" glass pane, and one 6"x6" glass pane, required for a C-130 A/C airframe change #341.
97046	12/28/00	Hang up bulletin board in office across from the elevator.
97066	12/29/00	Can't get front door to close, need fixed ASAP unable to lock door
97068	12/29/00	Cannot get door to close all the way. Won't be able to lock up when I leave today. This is urgent. Also letting in cold air.
97091	12/29/00	Repair or replace all damaged wood on H-46 wrap around stands. Stands located in the H-46 hangar and in storage yard.
97306	1/3/01	Tile within the "Break room" behind the training office in bldg 133 needs replacing. The tile has buckled and lifted off the floor due to a past water leak in the room which required the door be replaced.
97334	1/3/01	Prop shop paint area has 1-2" gaping hole. Walls not flush against each other patch job.
97335	1/3/01	Remove wood shelving in the Technical Library. One shelf is sagging and could be dangerous due to an employee sitting very near this shelf. Two other shelves are no longer needed.
97346	1/3/01	Need keyboard tray realigned
97449	1/4/01	Cut plywood for varazon press

Ticket Number	Date	Description of Problem
97795	1/8/01	Door to secure area (inside door) does not shut properly. Results in door not closing properly when entering or leaving secure area from unsecure lab area This results in security breach as non-cleared personnel can access secure area.
97797	1/8/01	Request weather strip be placed on bottom of office door to prevent heat loss and block entry way for mice
97840	1/8/01	Please cut new Plexiglas diffusers for lights in paint booth
97857	1/8/01	Door return mech. to hazmat. Test area broken. Thanks
97997	1/9/01	Re-install rubber on C-130 cradle and re-install cradle inside holder.
98071	1/10/01	Wall cabinet needs hung in training leaders area in ordnance shop
98089	1/10/01	The concrete seam where the building floor meets the outside entrance (below the main doors when clogged) is cracked and jagged causing severe shakes and jolts to engines being pushed into and out of T64 test cell.
98148	1/11/01	Replace wood on F-4 stabalator dolly located at welding shop thank-you very much
98174	1/11/01	Need some Plexiglas and plywood cut as per instruction.
98202	1/11/01	Repair floor beams holding up floor grate in the clean shop.
98204	1/11/01	Repair wood skids
98218	1/11/01	Install wall and doors as per on site visit and task no. 110006.1
98231	1/11/01	Mount fire extinguisher and fix trailer door.
98234	1/11/01	Need to replace padding and wood on H-46 blade dolly located in the GSE compound. Thank-you very much and have a nice day
98351	1/12/01	The hydraulic closer hangs up the doors going into the head in the mezzanine room where the drink machines and the snack machines are.
98358	1/12/01	Sand and finish work bench top for shop 65100
98463	1/16/01	Threshold under door is loose. (in master gauge room) trip hazard.
98465	1/16/01	Doors will not close in mixing room
98476	1/16/01	Repair leg on lathe
98487	1/16/01	Install closure on door leading to roof. Discrepancy found during PM of the roof on Link #V484676.
98489	1/16/01	Replace set of doors as identified per PM of the roof on Link #V484667.
98495	1/16/01	Door to Ladies bathroom is broken, need to adjust the door actuator
98549	1/16/01	Closing cylinder on ladies bathroom door #W72 is loose and could fall off and injure someone. Please send someone to take a look at it. Thanks
98550	1/16/01	Door on Men's head is sprung and will not close. It is sprung from the cleaning contractors putting a wooden block in the top of it to keep it open and it has bent the upper hinge area on the door to where it is hitting the facing on the jam.
98558	1/17/01	Request bulletin board installation on wall in building 4188.
98605	1/17/01	replace fabric on CH-53 stab dolly located at carpenter shop thank-you
98675	1/17/01	Need skirting placed under desk

Ticket Number	Date	Description of Problem
98767	1/18/01	Repair exit door that is hard to open. Per fire inspection need corrected ASAP!
98768	1/18/01	repair and replace wood on (2) two each H-53 fuel cell boxes thank-you very much
98799	1/18/01	replace wood on F-4 stabalator dolly thank-you very much
98801	1/18/01	Hang cabinet on wall in office
98824	1/18/01	Need rubber replaced in landing gear build up stands rubber must be glued in stands are now causing damage to gear work stop please help
98828	1/18/01	Repair ceiling tiles. Tiles were damaged because of water leak.
98830	1/18/01	Have glass tops cut and installed on new desk in shop. Jon: 16leaj4
98833	1/18/01	Need a door stop for the outside door
98836	1/18/01	Replace rubber on H-53 upper hub dolly with teflon according to change thank- you very much
98849	1/18/01	Replace rubber on H-53 upper hub dolly with teflon according to change thank- you very much
98850	1/18/01	Replace rubber on H-53 upper hub dolly with teflon according to change thank- you very much
98892	1/19/01	Replace door closures with heavy-duty closures and install stainless steel plates to protect doors from carts, install removable pipe bollard with door stop near aisle way.
99054	1/22/01	Three pieces of 3/8 exterior plywood 40x 48 inches
99106	1/22/01	fix arm rest
99109	1/22/01	Install Bulletin Board in shop 6.2.96556
99129	1/22/01	Screws have broken on door hinge and door is hanging. Door is at the entry to the 4.0 Research & Engineering Group Head doorway. Please expedite.
99131	1/22/01	Cut plywood per instructions
99165	1/22/01	Door closer is leaking and not controlling door properly.
99209	1/23/01	Need casters replaced on chair front hall way towards co's office 1st door on right
99229	1/23/01	Sliding door in flushing area coming of the track could become a dangerous situation if someone tries to open it. Please hurry if you can.
99364	1/24/01	Repair or replace door closer between stripbarn and paint shop
99479	1/25/01	Replace damaged Grate in front of Lindberg Melting pot in foundry area of Heat Treat.
99490	1/25/01	Repair the following carts # 061632, 061661, 079985
99522	1/25/01	Put door sweep beneath conference room door, area 137
99538	1/25/01	Repair vinyl siding on building
99540	1/25/01	Replace missing ceiling tiles that were destroyed by steam leaks.
99546	1/25/01	Need to replace the rubber pads on a 3 step and a 4-step workstand located at the carpenter shop.
99578	1/26/01	Rotary Wing QA office has a staircase with a broken step. Staircase is located in the south corridor. Please Fix ASAP.
99587	1/26/01	Front door of 133 door closer fell off

Ticket Number	Date	Description of Problem
99604	1/26/01	Cut glass tops for 6 desktops and install. Use jon # 14meaj4.
99606	1/26/01	HDSC/SSE Room 4224. Sling Rack need to be re-attached to the wall.
99616	1/26/01	Repair top rail of cardboard berm fence and any damaged section of fence.
99634	1/26/01	Door closer is leaking and not controlling door properly
99664	1/26/01	Replace missing ceiling tiles in phone switch room next to Shop 94206. Loose insulation constantly blows into adjacent office areas. Causes discomfort and is dangerous to breath.
99671	1/26/01	Remove window as proposed conf room
99761	1/29/01	HDSC/SSE Room 4224. Sling Rack need to be mounted to the wall. This is the second ticket; first ticket # 99182 was closed; yet, the work had not been done.
99774	1/29/01	Need to replace padding on wood of CH-53 blade located at dog pound compound thank-you very much
99775	1/29/01	Need to replace padding on wood of CH-53 blade dolly located at dog pound compound thank-you very much
99810	1/29/01	Personal IQR cabinet needs a locking device installed
99864	1/30/01	Install new thresholds in doorways of office per customer's request. Send to R01.
99962	1/30/01	Data stand in AV8 hangar needs new Plexiglas lid with hinges installed.
100042	1/31/01	Pedestrian passage door in the back of sta 8 uncan area needs to be replaced. The present door has no doorknobs and no regulator to keep it from slamming.
100052	1/31/01	Install blinds, move shelves, build shelf table and hang bulletin boards
100069	1/31/01	Need to reattach door to desk
100083	1/31/01	Repair roof to accommodate air vent
100148	2/1/01	need to replace padding on H-53 stabalator dolly thank-you very much
100167	2/1/01	Door closure for 960 office is not working
100172	2/1/01	need to replace padding on H-53 stabalator dolly. Thank-you very much
100276	2/2/01	The door closer on the outside door of the south stairwell is broken. The screws securing it to the door have fallen out.
100306	2/2/01	Cut 3/4 inch plywood to measure 8'x 2'. Give ticket to carpenter shop.
100310	2/2/01	Request chairs in 930 Division Director's office be repaired. (loose joints)
100311	2/2/01	Data stand in AV8 hangar needs new Plexiglas lid with hinges installed.
100320	2/2/01	need to put rubber pad on feet of 3 step workstand thank-you very much
100331	2/2/01	We need two peg (display) boards made up in the t64 sub-assy area for tracking of production parts assembled and placement of available material for the t64 engine program.
100343	2/2/01	The outside door hinge is either broken or stuck, not allowing the door to open all fully. This may be a safety risk. The door is located on the left side of the building as you are facing the front doors.
100349	2/2/01	Please replace the Plexiglas light shields on the lights in both paint booths. bldg # 137 Small Component Paint Shop 93117B.
100383	2/5/01	Ceiling is sagging in the technical library and could be a hazard to all the employees in this area

Technical Exhibit 3.36, Page 10 of 30 Revised: 04/03/03, 11:01 AM

Ticket Number	Date	Description of Problem
100385	2/5/01	Repair wooden chairs in 930 division director's office be repaired (loose joints)
100418	2/5/01	Door hinge at top of emergency exit located on east side of building has been torn off, probably due to being opened in the windy weather.
100426	2/5/01	Repair wooden chair, joints are loose
100451	2/5/01	Door closer is not working on office door.
100527	2/5/01	Personnel door on hanger door on the A street side of hanger 3 (CH-46) is about to fall off it's hinges.
100547	2/6/01	Install and stain chair rail Mezzanine G 137
100561	2/6/01	need to replace padding on CH-53 blade dolly, thank-you very much
100603	2/6/01	Dislocated top hinge of double fire door in NOAP Lab. Security problem. Need fixed as soon as possible.
100690	2/6/01	Door closure is broken. This door enters into the sermetel paint room from the main hall.
100715	2/7/01	Please cut to length wood shelving boards as per instruction.
100725	2/7/01	need to replace padding on CH-53 blade dolly thank-you very much pa #65923070904
100741	2/7/01	replace wood and padding on CH-46 blade dolly. Thank-you very much sir
100751	2/7/01	Extend wall to ceiling in equipment room next to union office see for details.
100782	2/7/01	need to replace padding on H-53 stabalator dolly. Thank-you very much
100792	2/7/01	Provide twelve (12) ea plywood sheets 41"x75"x5/8" call for pick-up
100834	2/8/01	need to replace padding on CH-53 blade dolly thank-you very much pa #65923070904
100849	2/8/01	Replaced broken glass on fire bill bulletin on wall next to office.
100850	2/8/01	Cut plywood 3/4 inch double up and install on verson racks
100898	2/8/01	Replace counter tops of (incoming & outgoing counters) of shop 94203.
100933	2/8/01	Install retaining wall as per attached sketch
100936	2/8/01	Door at Supervisor's Office will not close In shop 93111b, cleaning shop
100982	2/9/01	Personnel door on hanger door on the A street side of hanger 3 (CH-46) is about to fall off it's hinges.
100984	2/9/01	Install more cork strips around perimeter of office.
101006	2/9/01	Install shelves in new cage enclosure to store tooling.
101019	2/9/01	Need 5 pieces of plywood 3/4" think cut for cart. Will provide other measurements when contacted.
101026	2/9/01	Interior wall is separating around window
101057	2/9/01	Attn: need to replace wood and replace padding with rubber on C-130 rudder/elevator. Thank-you very much
101100	2/10/01	Passageway door between clean room and dirty room is broken. Door pump is inoperable. Repair ASAP
101161	2/12/01	Wooden platform for hpt mra stand needs repaired.
101164	2/12/01	Repair wooden boxes for T-48 compressor 20 each for "g code "

Ticket Number	Date	Description of Problem
101165	2/12/01	Relocate bins and materials as per above requestor
101166	2/12/01	Repair wooden boxes for lpc blades. 10 each
101167	2/12/01	Repair wooden enclosure for datum scales
101169	2/12/01	Repair T-64 compressor rotor boxes 10 each.
101203	2/12/01	need to replace rubber on CH-46 fuselage cradle. Need it ASAP thank-you very much
101283	2/13/01	Repair ceiling tile in hallway to tech Library.
101310	2/13/01	Ceiling tiles in shop need replacing
101416	2/14/01	Replace hinge on (2) two Co2 Box's Numbers 22 & 32. Send work order to carpenter shop.
101420	2/14/01	Need 5 pieces of plywood 3/4" think cut for cart. Will provide other measurements when contacted.
101484	2/14/01	Need a cork board hung outside of Col's office and a picture relocated in the front hallway of building 137
101510	2/14/01	Re-attach a right rear desk leg of desk. Yesterday a move took place on Mezzanine C bldg 137 and power poles were installed today. With all the moving, the desk leg broke off.
101684	2/16/01	Need to replace the rubber on a vertical shaft dolly located at the carpenter shop
101705	2/16/01	Install partitions in 950 and 930 Div office, Mezzanine C, bldg 137. This job is being done Friday, Feb 16 all day, by Coastal Waterproofing. Thanks!
101717	2/16/01	Replace wood on a cH46 blade dolly located at the welding shop for work.
101975	2/21/01	Cut 2 each clear Plexiglas for desk tops, 30" X 59 1/2"
102017	2/21/01	Please repair the floors in can 1355, 1378 and 1383.
102117	2/22/01	960 Division Secretary has approximately 6 corkboards that need to be wall mounted. (6.2.960), is POC 960 Division Office, Mezzanine A, Bldg 133
102152	2/22/01	The wooden door within the 96000 Training Office has the paneling peeling off where it catches on the doorframe edging. Request the door be repaired or replaced.
102153	2/22/01	Please repair or replace Door Closer to the Tool Room, in bldg 4225.
102308	2/23/01	Book shelf is weak
102345	2/23/01	need to replace rubber on CH-46 double vertical shaft dolly thank you very much
102350	2/23/01	Need to replace padding and wood on H-46 blade dolly located in the GSE compound. Thank-you very much and have a nice day
102363	2/23/01	2 White boards, corkboard, movie screen, and clock need to be hung in the conference room.
102385	2/24/01	Request one 3/4" plywood board be cut to the following dim. 19 3/4" x 28 3/4" for pick up.
102437	2/26/01	Need to replace the padding on an H53 stabalator dolly located at the carpenter shop.
102448	2/26/01	Request plywood be cut to length, width and quantities requested below: 3/8 X 19-3/4 X 13-1/2 50 each, 3/8 X 28-3/4 X 19-3/4 50 each, 3/8 X 26-3/4 X 17-3/4 10 each, 1/4 X 28-3/4 X 19-3/4 15 each. Plywood will be used on the tops of rollaway toolboxes

Ticket Number	Date	Description of Problem
102536	2/27/01	Need a piece of Plexiglas cut 22" x 34".
102543	2/27/01	Need to replace the wood and padding on a CH-53 blade dolly. Dolly is located in the dog pound storage area Call when ready to work.
102609	2/27/01	Repair floors in bldg 1377 as needed poc can 1378
102611	2/27/01	Install fire extinguisher
102614	2/27/01	Repair seam in concrete floor at foot of stairs descending from Mezzanine 19-2 and 19-3. Seam runs approximately 27 feet. Individual twisted foot and was injured.
102718	2/28/01	Need large hole drilled in cabinet in office for satellite receiver plug to plug into wall.
102774	3/1/01	Floor plywood broken in can 1385 investigate and provide
102830	3/1/01	Replace wood as necessary and the rubber on F-4 outer wing dolly.
102842	3/1/01	Please install rubber pads on work stand as per instruction.
102864	3/2/01	Remove existing clock and hang new clocks
102865	3/2/01	Replace canvas and felt pad on the edge of 15 H46 helicopter stands. Must have canvas and felt before they can be used.
102866	3/2/01	Remove existing rotten wood floor decks on the three remaining H46 work stands. Replace stands with new plywood.
102883	3/2/01	The floor in can 1383 is rotten and needs repair.
102892	3/2/01	Frame Picture-30 yr award.
102939	3/2/01	Repair floor at entry way of can
102954	3/2/01	replace rubber as needed and as necessary on CH-53 blade dolly. Thank-you very much
102975	3/2/01	Fill in hole in wall, tool room d, to reduce noise exposure in tool room from compressors installed in adjacent room. Two 4" conduit pipes run through hole.
102979	3/2/01	Repair 2 ea conf wooden chairs
103094	3/5/01	replace rubber padding on CH-53 blade dolly. Thank-you very much
103108	3/5/01	Request replacement/repair screws in wood frame on upholstered executive chair. Chair in good condition but continued use is likely to damage chair and someone could get hurt.
103119	3/5/01	Frame picture 30 yr award
103152	3/6/01	I need a board 2" by 12" by 19' for our Lowboy to bring back a H-1 aircraft from New River. I need ASAP.
103172	3/6/01	need to replace the padding on a e2/p3 prop dolly. Thank-you very much
103221	3/6/01	B-200 Front door stop/spring completely broken off allowing door to swing free in wind. Backdoor spring/stop needs adjusting to ensure door closes/locks when released (secure door).
103275	3/7/01	Access to the second floor level by ladder is unsafe, Please have this problem corrected.
103300	3/7/01	Need ergonomic keyboard platform installed under desktop ASAP. Requirement from workers compensation injury. Thank you.
103358	3/7/01	Mini blind on front door broken. needs fixing or replacing.

Ticket Number	Date	Description of Problem
103406	3/8/01	Make base for monitor 9 inches high
103449	3/8/01	Request door opener be adjusted at top of door in the SBU area (elevator side), Mezzanine A, to prevent rubbing.
103460	3/8/01	Frame picture 30 yr awards
103469	3/8/01	Replace cracked and broken ceiling panels in 6.1.523 area, Mezzanine 19-2, bldg 137.
103492	3/9/01	Check closers on fire doors some do not close properly
103493	3/9/01	Need to have 6ea Plexiglas windows cut for the tow tractors as per sample.
103521	3/9/01	The office door of the supervisor needs to be fixed as the part that enabled the door to close on its own, is now broken off.
103666	3/12/01	Door for telephone box fell off wall. in front office area re-attach the wooden cover for the pay phone to the wall.
103733	3/12/01	Repair floor in bldg 1378 as needed. Repair structural corrosion as needed.
103814	3/13/01	Hang HEAVY electronic white board in Bldg 4470, upstairs. Est. Two men, 2 hrs.
103815	3/13/01	need a piece of 5/8" plywood cut 43 1/2" x 15". will pick it up when ready. Call when ready. Thank-you very much
103822	3/13/01	Shave bottom of supervisor's door to provide adequate clearance for new carpet.
103870	3/13/01	Microwave oven will not fit on shelf under cabinet top. About 3/4 of an inch needs to be removed from the counter top lip to allow Microwave to fit.
103914	3/13/01	Sliding shelf in desk won't pull out
103923	3/13/01	Need two 59 inch by 23 ¾-inch, 3/4-inch thick plywood for shelf on cart. Shelf disappeared last night. Cart is located at station 65, main mrb room, near vending machines in bldg 133.
103932	3/13/01	Purchase material and make repairs to trailer #97-41256. Need 2 1/2 x 6 oak wood for repairs.
103969	3/14/01	Need 2 ea (2 x 20)-80 inch long and 1 ea 28 x 80 (3/4) plywood cut
104008	3/14/01	Fire extinguisher mount located in paint area of the prop shop in B-137 needs to be relocated. The mount sets to low and can cause damage to a blade. The mount should be raised another six inches, request this be taken care of as soon as possible.
104077	3/14/01	Repair doors as needed. One door in the break area, leading outside and one in the propeller assemble area
104132	3/15/01	Need to cut out 2 sections of a H46 fuselage cradle as marked. The cradle will be delivered to the carpenter shop
104181	3/16/01	Cut several pieces of Plexiglas as request
104182	3/16/01	Repair bench as per instruction.
104265	3/16/01	Cut plywood to fit shelves at verson press I heat treat see for details
104308	3/19/01	Door leading to 960 Division Office, Mezzanine A, Bldg 133 has been damaged and needs repair. Door leading into large 960 SBU Area, Mezzanine A, Bldg 133 needs door closure installed.
104325	3/19/01	Doorframe for the fire door in the Oil Lab has been damaged beyond repair. Demolish the existing frame and replace with a new UL approved wrap around fire door frame with a minimum rating of 1 1/2 hours.

Technical Exhibit 3.36, Page 14 of 30 Revised: 04/03/03, 11:01 AM

Ticket Number	Date	Description of Problem
104381	3/19/01	A workstation was made and a now there are splinters on bottom edge of table. Needs to be rounded over
104398	3/19/01	My computer keyboard is mounted under my side desk credenza. The mount/roller/tray where the keyboard sits is broken. It needs some screws & needs to be adjusted. (The EIN number above is for my computer.)
104444	3/20/01	FOD display box located along main hallway on the bulletin board is damaged and has an exposed nail. (Possible human injury waiting-to-happen.)
104464	3/20/01	need to replace padding on CH-53 blade dolly. Thank-you very much
104481	3/20/01	New lab exterior door (facing flight line) needs weather seal. Check problem and install weather-strip if needed and within monetary limit.
104605	3/21/01	Need to replace the padding on a AV8 vertical fin dolly located at the carpenter shop
104617	3/21/01	Wind has damaged the doors on bldg 133 penthouse 10 & 11. Evaluate damage and Paid 3/28/01 DCT \$897.00
104689	3/22/01	Please repair Door to NEW Thermal Image Room. Top hinge screws are stripped/loose and will not hold door and it strikes jam as it closes. Thank you
104698	3/22/01	The non-skid treads on the stairs leading to storage mezzanine (the old da storage area column bb-27) are worn. Replace them soon as possible. The present treads present a safety hazard (slipping hazard)
104710	3/22/01	Replacement of ceiling tile. In October, we had a leak in the floor above us causing a ceiling tile to collapse. The leak was fixed but we are still waiting for our replacement ceiling tile. If were on the third floor it would make for a great skylight.
104748	3/22/01	Repair seam in concrete floor just inside H-46 hanger. Do this on Monday, May 28 (holiday)
104768	3/23/01	Relocate whiteboard, corkboard, TV stand, 2 printers and printer tables from old office bldg 163 to his new office, bldg 137.
104773	3/23/01	Cut 1 sheet plywood 3/5 thick 35 5/8 square. Cut one sheet 3/4 4 x 8 feet
104775	3/23/01	Relocate glass door bookcase to new office, bldg 137 and make another shelf to replace missing one in bookcase.
104791	3/23/01	Repair desk as per instructions
104818	3/23/01	Install wooden shelf in enclosure. if you can expedite this I would appreciate it. It is for the enclosure just put in for me. Thanks
104835	3/23/01	Need someone to bolt down two shelves on cart located at station 65. Need to drill through metal frame into plywood. Located near vending machines in bldg 133.
104847	3/23/01	Adjust door to office, it bumps, Attn: 65500
104878	3/24/01	Requesting bonding room door be repair so that the door will shut completely.
104902	3/26/01	The non-skid treads on the stairs leading to storage mezzanine (the old da storage area column bb-27) are worn. Replace them soon as possible. The present treads present a safety hazard (slipping hazard)
104930	3/26/01	Replace torn, stained, and messed up ceiling tiles in new office, bldg 137.
104931	3/26/01	need to replace padding on CH-53 blade dolly. Thank-you very much
104936	3/26/01	Request to have desk repaired. It needs to have a back covering to hide exposed wires. Also request to have two 4' wall sections installed in front of desk.
104944	3/26/01	Need 30 x 60 of Plexiglas cut

Ticket Number	Date	Description of Problem
104949	3/26/01	CH53 needs plywood 3/4 x 4 ft x 8 ft.
104992	3/26/01	Repair holes in walls, ceilings, and floor of second story mechanical room. Notify Fire inspector when work is complete. Fire Prevention Survey.
105087	3/27/01	Safety hazard: consumable material storage door- near bathrooms is hard to open/close. Easy to smash fingers.
105098	3/27/01	Some time ago we had a coat rack made and installed in the men's locker room. Now it is carping and coming off the wall dropping the coats in the floor. Can you fix?
105117	3/27/01	Fix broken ergo chair (minor repair).
105145	3/28/01	Request repair of broken back on wooden conference room chair.
105172	3/28/01	Install keyboard tray
105177	3/28/01	Cut as per instructions
105225	3/28/01	Replace and paint yellow 1" x 12" x 8' board on parts cart.
105299	3/29/01	Need to replace the padding on a cH53 blade dolly. pa number 65923046814
105351	3/29/01	Exit/entrance door to the mixroom is inoperable. Safety hazard. Request urgent repair.
105371	3/30/01	Put new felt in 2 ea display
105469	3/30/01	Install shelf on wall
105564	4/2/01	Repair bottom desk drawer.
105644	4/3/01	To install 2 keyboard drawers for 65900.
105646	4/3/01	Need to replace the wood on a e2/p3 prop cart pa number 65889513192. Cart is located at the carpenter shop
105657	4/3/01	Need to replace the padding on the inserts from a C-130 rudder/elevator dolly.
105671	4/3/01	Repair wood door and hinge on cabinet.
105702	4/3/01	6.3.65500. Please nail shipping box back together for Kahn water brake. Box in bldg 1006.
105719	4/3/01	Division director's saloon-type door - sticking slightly and squeaking loudly. Very distracting and obnoxious.
105753	4/3/01	Door closer broken and hanging from frame, main entrance of bldg 4224
105767	4/4/01	Redo wood flooring between tanks
105768	4/4/01	replace wood on three (3) shelves on parts cart. Thank-you very much
105800	4/4/01	Install keyboard tray
105826	4/4/01	Install updated map in large frame located behind desk.
105938	4/5/01	Install blind in window
105946	4/5/01	Install door closure on entrance to 960 SBU.
106001	4/6/01	Doors on station 8 sticking on ndi auto pt
106013	4/6/01	Break room door will not open/ can't get in
106014	4/6/01	Need mirrors replaced in ladies bathroom located in small paint shop at bldg 137/ upstairs

Technical Exhibit 3.36, Page 16 of 30 Revised: 04/03/03, 11:01 AM

Ticket Number	Date	Description of Problem
106035	4/6/01	need to replace padding on AV-8 vertical fin dolly located at your shop. Thank-you very much
106037	4/6/01	need to replace rubber padding on feet of 3 step workstand. Thank-you sir very much
106052	4/6/01	Remove broken ceiling tiles from the 1st. Floor, at the logistics end.
106096	4/7/01	Hang small bulletin board in composite dirty room. Shop supervisor has bulletin board
106179	4/9/01	Provide twelve (12) ea 5/8" thick sheets of plywood measuring 75"L x 41"W.
106229	4/9/01	Replace door closure in maintenance Shop
106327	4/10/01	Need to replace the wood on 4 ea H53 tail blade dollies located at the paint area
106329	4/10/01	Install fire extinguisher in 960 SBU Division Office on Mezzanine A bldg 137.
106331	4/10/01	Need to replace the rubber on a H46 aluminum workstand located at the carpenter shop.
106358	4/10/01	Replace water damaged ceiling tiles in front lobby. Request this be completed before the IG/ISO Command Reception. Needs completed by 7 May 01.
106403	4/11/01	Cut piece of lexan as per sample.
106419	4/11/01	Remove fire extinguishers from walls in empty offices/rooms in bldg 163 and relocate PIC box.
106466	4/11/01	Hang mailboxes, org board, misc odds and ends; small refrigerator and microwave moved; other stuff taken to Connor W/H. Est. is 2 men, 6 hrs.
106473	4/11/01	Saw or remove post in space 4/14 in front of bldg 133
106530	4/12/01	Remove wall mounted bookcases and re-hang in downstairs office, new annex, B133 (has cinder block walls). Est. is 2 men/ 2 hrs.
106642	4/13/01	Break down wooden boxes, segregate, and load into proper roll offs.
106781	4/16/01	Remove 2 wall-mounted bookcases from Mezzanine B & D paint and reinstall on 960 SBU Office.
106787	4/16/01	Penthouse doors on roof of building, ein #'s 65923x00932, 00935, and 00937. The hinges are broken on access doors. Hinges need to be spaced out flush with face of doors and safety chain installed on each door.
106858	4/17/01	I need two bulletin boards mounted on the wall here in shop 94301. Install bulletin boards if within monetary limit.
106901	4/17/01	Relocate shelves in production control area/ Shop 96332
106925	4/18/01	Take apart cabinets under Mezzanine C of Bldg 133. This needs to be done Wed. morning. Est. is 2 men / 2 hrs
106957	4/18/01	Install two bulletin board in shop 94301 thanks
106960	4/18/01	6.1.526 has request two bookcases removed from old 6.1.526 office under Mezzanine C painted and reinstalled in 960 SBU Mezzanine A. Bookcases should be painted same color as adjacent bookcases.
107016	4/18/01	Need to replace the padding on a H53 stabalator dolly located at the carpenter shop.
107028	4/18/01	Please install rubber on H-53 Tailgate Dolly.
107122	4/19/01	Relocate bookshelves and cabinets and install as necessary in new Security office per customer's specifications. Est. is 2 men / 4 hrs.
107224	4/20/01	Need to cut a piece of plywood 4'x 5' 1/2 inch thick. Call for pickup.

Ticket Number	Date	Description of Problem
107243	4/23/01	Cut 3/4" plywood 11 1/2" x 74 3/16". For use in rudder fixture.
107269	4/23/01	Fix small area of flooring in can 1385
107337	4/23/01	Level the dropped ceiling and replace damaged tiles.
107359	4/24/01	Install two fire extinguishers on Mezzanine B bldg 137.
107415	4/24/01	Please repair the bulletin board brought to you. Remove center beam (divider), and fix the doors to fit.
107476	4/25/01	Replace wooden sides, hinges, slotted ends, padding, canvas as required/prep, prime and paint as required per site visit parts carts nos. 64787, 61645, 079382 and 61633.
107489	4/25/01	Request carpentry shop install a piece of 3/4" plywood in the bed of Trk Pick Up 42-40090.
107536	4/25/01	Need a 21" x 24" flat piece of 3/4 inch plywood cut to set new laser printer on (set on top of filing cabinet). Need immediately & will pick up!
107659	4/26/01	Need to have cabinets relocated to another area within Acceptance Transfer Branch Area
107677	4/26/01	Office door for 95774 supervisor is broken at bottom hinge; needs to be repaired before it falls off hinge.
107727	4/26/01	Relocate wall mounted cabinets in ATB in Bldg 1665. Est. is 2 men / 1 hrs.
107737	4/26/01	Need to repair door closure on door next to the coke machine. Screws are loose
107810	4/27/01	Wooden tables in swashplate area must be reinforced. One of the tables has very loose legs and us no longer safe for use as a disassembly table.
107836	4/27/01	Cut 3/4" plywood as per my instructions for shelves.
107944	4/30/01	Small front door off hinge will not close.
107987	5/1/01	Repair wood sides and ends of carts, prep, prime and paint as per on site visit; carts numbered 048678, 060428, 061715 and 066468
108105	5/2/01	Need to replace the padding on 2 ea Prop carts located at the carpenter shop.
108117	5/2/01	Cut (18) pieces of plastic as per sample
108154	5/2/01	Replace three wall-mounted bookcases with lockable doors.
108199	5/3/01	Door closer on back door, personnel door, customer service bldg, broken needs replace ASAP, safety concern, someone might hit head on closer.
108225	5/3/01	Replace one water stained 2'x 4' ceiling tile located in upstairs hallway adjacent to office. Please complete prior to 5/11/01.
108306	5/4/01	Modify wooden bookcase for person in Ordnance Shop. Est. is 1 man / 2 hrs.
108313	5/4/01	Move cabinet mounted on wall to another wall, and take down telephone lighted board - no longer in use.
108468	5/7/01	01/18/01 a request was submitted to modify workstands for two vtls. A filler was added, but a new 3/4" top was never added. Contact for details.
108500	5/7/01	need wood replaced on bottom of eaps dolly and rubber put on the two (2) pipes on it too thank-you very much
108503	5/7/01	need wooden box and wooden inserts at the bottom of the e2/p3 dolly replaced. Thank-you very much
108634	5/8/01	Repair blade, per instructions
108661	5/8/01	Replace out of place, missing, or broken ceiling tiles in new 960 SBU, Mezzanine A, Bldg 133.

Ticket Number	Date	Description of Problem
108720	5/9/01	The second tread is bent on the outside stairs leading to the roof of building 133 thus creating a safety hazard. Repair or replace as necessary.
108721	5/9/01	Remove plastic and strips off outside of smoking shelter at bldg 4225.
108731	5/9/01	Make a small enclosure to cover exposed pipes and install work surface in cubicle, Bldg 159. Est. is 2 men / 5 hrs.
108782	5/9/01	Install cabinets in Mezzanine A
108868	5/10/01	replace wooden inserts on CH-46 blade dolly thank-you
108869	5/10/01	replace wooden inserts on CH-46 blade dolly thank-you
108870	5/10/01	replace wooden inserts on CH-46 blade dolly thank-you
108927	5/10/01	Relocate wall-mounted bookcase to opposite wall in soon-to-be office in Bldg 159 and touch up nail holes in wall.
108955	5/10/01	Men's restroom door slams when closed but comes back open and remains open. Please fix this so it closes and stays closed.
108969	5/10/01	Repair legs on 53 dolly stands. Safety hazard.
109002	5/11/01	Install ceiling tile in deputy division director's office, destroyed during water leak between floors. Repair of pipe made in winter 2000.
109015	5/11/01	Repair file drawers on modular furniture
109023	5/11/01	Remove huge bookcase from office - Mezzanine A, B133; and relocate and assemble in old 960 Action Center. Est. is 2 men / 2 hrs.
109024	5/11/01	Set up free standing bookcases and mount wall-mounted bookcases as necessary in 960 SBU, Mezzanine A, B133. Est. is 2 men / 4 hrs.
109039	5/11/01	Need to replace the padding on a H53 blade dolly. Dolly is located in the dog pound storage area
109040	5/11/01	Need to replace the padding on a H53 blade dolly. The dolly is located in the dog pound storage area
109060	5/11/01	Patch/prep floor, remove cove base, install new carpet as per customer's selection and install new cove base, includes rearrangement of furniture to accommodate carpet install, dispose of debris
109066	5/11/01	Replace wooden cradle ends and sideboards on carts, sandblast and paint as required per on site visit, carts nos. 80040, 0726, 8561342 and76450. Task no. 113492
109164	5/14/01	Ceiling tiles in shop are missing and need replacement. Shop needs 7 tiles replaced
109185	5/14/01	replace rubber on CH-46 tail fuselage dolly. Thank-you
109238	5/15/01	Shop suggestion box need to be mounted to wall
109286	5/15/01	Shop suggestion box needs to be mounted to wall
109400	5/16/01	Need to replace the wood on a AV8 crash dolly. Dolly is located in the GSE dog pound storage area Call when ready to work.
109403	5/16/01	Door has blown off penthouse # 3. Re-hang door.
109476	5/17/01	Door needs to have a doorstop installed on the bottom to hold the door open. Right now a garbage can is being used as a door stop. See for more information.
109552	5/17/01	Repair or replace the door on penthouse # 3, roof of 133 it is the door on the west end of penthouse, it is off and lying on the roof.
109575	5/18/01	Please install keyboard.

Ticket Number	Date	Description of Problem	
109589	5/18/01	Re-glue partition strip small men's head, front office, Bldg 137	
109609	5/18/01	Need to mount card holders to wood as per instruction	
109610	5/18/01	Cut door in middle of cabinet for access. Install hinges and handle. POC: Shop 6.3.65100.	
109632	5/18/01	Need someone to please attach a wooden shelf we have in our shop to the wall. Thanks so much.	
109648	5/18/01	Flags hanging from overhead on A Street end of AV8 hangar need reattached, looks like weight rod is about to fall out, will be a safety hazard	
109707	5/21/01	Need to replace the wood on 3 ea Av8 fuselage dollies located next to the 84 paint shop.	
109710	5/21/01	Need to replace the wood on H53 tail blade dollies located at the 84 paint shop.	
109721	5/21/01	Repair or replace the door on penthouse # 3, roof of 133 it is the door on the west end of penthouse, it is off and lying on the roof.	
109752	5/21/01	Hinge on cabinet doors need to be fixed	
109773	5/21/01	Ceiling tiles are falling down in the eatery area. This could be due to leaking A/C, which has been a problem all over the area today.	
109783	5/21/01	The door going into the women's restroom upstairs bldg 4224, does not close completely and is hard to open. The door seems to be dragging and sticking.	
109871	5/22/01	Remove, relocate, and reattach work surface and overhead cabinet in bldg 159 upstairs. Est. is 2 men / 1 hr. DO this NLT Friday, May 25.	
109884	5/22/01	Replace wet ceiling tiles in the main aisles that were damaged from stopped up a/c drain	
109900	5/22/01	Replace damaged ceiling tile in front office area, clean water in carpet from leaks in front and back of bldg Repair the hot water leak on vav box.	
109942	5/22/01	We need to have two "L" bracket shelves mounted in the supervisor's office, one for the PA receiver, and one for the PC printer.	
109981	5/23/01	Install handicap ramp on gazebo	
109982	5/23/01	Install shelves as per on site visit	
110020	5/23/01	Repair holes in ceiling to prevent avenue for fire, holes in 2 rooms.	
110031	5/23/01	American flag is wrapped around hoist "I" beam	
110203	5/24/01	Purchase and install fire extinguishers for elevator mechanical rooms - locations - Bldg 137 (3), Bldg 133 (1), Bldg 4224 (2), Bldg 4225 (1), Bldg 200 (1), Bldg 4470 (1), Bldg 245 (1), Bldg 129 (1) TOTAL OF 11	
110287	5/25/01	Need to replace the padding on a H53 blade dolly located at the carpenter shop.	
110364	5/29/01	Shop needs to have a wooden mold stand for E-2 rubber boot assembly manufactured Qty 2	
110410	5/29/01	replace padding on inserts on H-53 blade dolly. Thank-you	
110438	5/29/01	Request newly installed toilet paper dispensers be repositioned in all handicapped restroom stalls in bldg 200. Dispensers need to be moved up approximately 12 inches so they will not interfere with handrails. Thank you.	
110488	5/30/01	Requesting new step for PC building. The step that are there are a safety hazard, they are falling apart.	
110489	5/30/01	Drill one hole in floor panel in computer room to route power cord to power source. POC for location.	

Ticket Number	Date	Description of Problem	
110495	5/30/01	Remove 2 glass door bookcases that will be accessed and swap out standard desk with a LH secretary desk in new Security Office, Bldg 137.	
110496	5/30/01	Drill one hole in floor panel in computer room to route power cord to power source. POC for location.	
110519	5/30/01	Requesting new step for PC building. The step that is there is a safety hazard, they are falling apart.	
110530	5/30/01	repair H46 skin preparation table	
110533	5/30/01	need to replace the wood and rubber on the AV-8 stab dolly. Thank-you sir	
110603	5/31/01	Please reinstall the ITN television in can 1380 thank you	
110611	5/31/01	Please install/repair keyboard tray to desk in office. Thanks.	
110625	5/31/01	Repair/replace wooden steps leading into the production control area of building. Existing steps are rotten and present a safety hazard.	
110638	5/31/01	Top shelf on a wall mounted bookcase needs reinforcement. The shelf is sagging due to heavy books and they cannot get the books underneath out. Other shelves have already been reinforced.	
110648	5/31/01	Need to replace the rubber on a H46 vertical shaft dolly located at the carpenter shop.	
110731	6/1/01	To have some udaps card racks hung on wall	
110734	6/1/01	To have a padded wooden box made to hold canisters on a cart, per safety regulations. I do have a drawing of what I'd like to have made. please call before starting this project and someone will bring the drawing to you. this is a work stoppage.	
110744	6/1/01	Top shelf on a wall mounted bookcase needs reinforcement. The shelf is sagging due to heavy books and they cannot get the books underneath out. Other shelves have already been reinforced.	
110745	6/1/01	Repair/replace wooden steps leading into the production control area of building. Existing steps are rotten and present a safety hazard.	
110746	6/1/01	To have some udaps card racks hung on wall	
110852	6/4/01	Ceiling tile out of place in hallway above the stairway. Item written up during a Fire Marshal inspection.	
110927	6/4/01	Two high-back upholstered desk chairs need repair. Similar problem to previously reported & repaired units. Call POC for details if necessary.	
110998	6/5/01	Leaking again, ceiling tiles still not replaced, dignitaries coming in and it is a mess.	
110999	6/5/01	The Plexiglas cover for scrubber AOH-1 is cracked and is leaking scrubber solution. Need to have a new cover and rubber gasket made. For dimensions please call Hazmat.	
111001	6/5/01	The Plexiglas cover for scrubber AOH-1 is cracked and is leaking scrubber solution. Need to have a new cover and rubber gasket made. For dimensions please call Hazmat.	
111060	6/5/01	Hang a corkboard on a wall 2nd level Condo Mezzanine, bldg 137. Est. is 2 men x 1 hr.	
111120	6/6/01	Remove wall sections to determine cause of water leak, dispose of debris, clean up as required and as per site visit	
111172	6/6/01	need to put rubber inside the bottom piece of H-46 vertical shaft dolly. Thank-you very much	

Ticket Number	Date	Description of Problem		
111230	6/7/01	This not a major problem but your type of problem section only had major. We need a hole caused by the doorknob repaired and we need a doorstop to keep it from happing again.		
111244	6/7/01	Shoe molding coming off in the hallway NEED FIXED ASAP		
111294	6/7/01	The Plexiglas cover for scrubber AOH-1 is cracked and is leaking scrubber solution. Need to have a new cover and rubber gasket made. For dimensions, please call Hazmat.		
111302	6/7/01	Replace padding on AV8 vertical fin dolly		
111307	6/7/01	Replace padding on AV-8 vertical fin dollynote: previous ticket for this had wrong pa # annotated-ticket #111302		
111373	6/8/01	Repair or replace picnic table on A street end of 4224, safety hazard		
111377	6/8/01	The celetex is falling down in office and needs to be repaired/replaced. Office is located by the entrance to the machine shops - bldg 137. It used to be the union office. Call for directions if needed		
111588	6/11/01	Door closure needs adjusting or replacing on door leading into building 133, parking lot side, by passenger elevator. Door slams when closed.		
111726	6/12/01	replace rubber padding on AV-8 vertical fin dolly. Thank-you very much		
111744	6/12/01	The stairs above the tech library have worn and broken strips of rubber. They are peeling chunks of rubber and the rubber is not all coming off. This is a definite tripping hazard and should be addressed as soon as possible.		
111766	6/13/01	Repair various wood work type items including door trim, closet enclosure, cover plates for access panels and walls as per site visit		
111776	6/13/01	Modify crate as per instructions.		
111824	6/13/01	Modify stud protector covers		
111836	6/13/01	Replace ceiling tiles that fell as a result of leaking pipes. We are losing much air conditioning because of this. Please assign ASAP.		
111840	6/13/01	need to replace wood and padding on (5) five ea e-2/p-3 prop dollies pa.# 075276, 075277, 074702, 513247, and 074700. Thank-you very much		
111885	6/14/01	Move plywood covering hole where rail for hoist 296 passes through wall. Move to opposite side of wall. End truck can hit plywood before end stop.		
111890	6/14/01	The ceiling panels keep blowing up between the entrance doors at the lobby of bldg 137 and the entrance at the VTC Room. Replace these panels with heavier panels that won't blow out. Try to match design as close as possible.		
111906	6/14/01	There is a hole in the wall behind the entryway door where the door handle went through. Please repair		
111945	6/14/01	Doorstops need replaced on all 4 doors of the main lobby Mr. Fitzgerald from Security called and said the CO would like this done ASAP - (06/15/01)		
111950	6/14/01	Request raising (2) desks to appropriate height to allow kneehole to be used by taller team members. Check for details/possible solution when he was out here last week.		
111953	6/14/01	Re-hang shelves in Graphic Arts and hall away waste		
111960	6/14/01	Need to replace the wood and padding on a cH46 blade dolly located at the carpenter shop		
111968	6/14/01	Need to replace the padding on a AV-8 stabalator dolly located at the carpenter shop		
112018	6/15/01	replace both wooden inserts on CH-53 universal tank dolly. Thank-you		

Technical Exhibit 3.36, Page 22 of 30 Revised: 04/03/03, 11:01 AM

Ticket Number	Date	Description of Problem	
112035	6/15/01	replace rubber padding on the bottom of (7) seven each H-46 vertical shaft dollies. Thank-you very much	
112051	6/15/01	Door broken, slams shut.	
112072	6/15/01	Repair and or replace /only if absolutely necessary (6) wooden crates (6w x 3h x 12L) (4w x 5h x 11L) (28"w x 13" x 5L) (49"w x 6h x 6L) (6w x 26"h x7l) (38"w x 2h x 8L)	
112390	6/20/01	Replace ceiling tile that was damaged from a leak in the ceiling. Leak is repaired, ceiling tile has fallen.	
112396	6/20/01	Need to cut a piece of lexon for flightline truck	
112424	6/20/01	Replace tile in shop 96332.	
112427	6/20/01	Broken desk drawer left side. Need to have it fixed.	
112486	6/21/01	Remove wooden 'cubbyholes' from wall facing Mezzanine C, bldg 133 and install wooden bookshelves per customer's request. Also remove wooden signs from hallway walls. Est. is 2 men working 6 hrs.	
112522	6/21/01	Need missing plywood shelves replaced. Property account # 659230689390.	
112526	6/21/01	Need missing plywood shelves replaced. Plant account # 65923-068390. Talk to sta 6.	
112673	6/25/01	Remove damaged plastic door curtains. Plating shop, bldg 4032	
112682	6/25/01	Repair wood on CH-53-E fuel cell box. Send work order to bldg 84 carpenter shop. Box is at carpenter shop.	
112730	6/25/01	Repair or replace wall in control room. Rotten wood at bottom of wall.	
112799	6/26/01	Door closer to mixing room is hanging up, needs adjustment.	
112911	6/27/01	Closure on entrance door needs adjusting or replacing. thanks!	
112974	6/27/01	Attn: WC-50 - in support of ticket #493779 sprinkler repair, need cabinet cut off at top, and repair ceiling.	
113099	6/28/01	Relocate mailboxes and hang two other items on wall Mezzanine C, Bldg 133. Est. is 2 men working 3 hrs.	
113173	6/29/01	Need to replace the rubber and attach the braces on 2ea C-130 tank pod cradles located at the carpenter shop.	
113174	6/29/01	Line with felt or foam T-62 apu transportation boxes Stencil with T-62 apu rotors return to shop 94404	
113189	6/29/01	Drop ceiling tiles missing leading to Mezzanine H. This is the side with all the offices	
113282	7/2/01	Plywood in front of secretary's desk needs to be rounded off and stained or painted. People are hitting their hands on the sharp edge and skirts have been caught on it. Thank you! Round edges and finish to match existing.	
113292	7/2/01	Need to replace rubber on bottom of feet. Thank-you	
113302	7/2/01	Permanently attach bookcase to desk. Investigate problem and see if the bookcase is a safety hazard. If it is, determine a way to attach the bookcase to the desk without putting holes in the desktop.	
113471	7/5/01	Automatic Closure Devise on Break Room BROKEN/ Please repair or replace ASAP	
113473	7/5/01	Need to put rubber on cH46 tail section dolly located at the carpenter shop. This dolly is needed on the H46 line ASAP.	
113595	7/6/01	Request openings be cut as required to accommodate printer in countertop.	

Ticket				
Number	Date	Description of Problem		
113715	7/9/01	Repair the remaining six wagons as per list.		
113740	7/10/01	The main entrance door to Suite 62 has settled and is dragging on the threshold. Needs repair.		
113750	7/10/01	Provide sides on existing shelving units as per site visit. Provide doors as required.		
113799	7/10/01	Remove the upper portion of plywood separating the two offices to improve the air flow.		
113968	7/11/01	Repair the deteriorated wall around the window air conditioner for the office area		
113971	7/11/01	Remove and relocate bookcase from empty room of Mezzanine C, bldg 133 to office per instructions and mount on wall. Est. is 2 men / 4 hrs.		
114043	7/12/01	Relocate position of keyboard on new workstation in Trailer 25. Est. is 2 men / 1 hr.		
114061	7/12/01	Need to fix soap dispenser in men's head at PMB.		
114082	7/12/01	Requesting shop blade 24 dollies be repaired. Replace wooden petitions.		
114145	7/13/01	Shelf in office needs reattached to the wall. It is about to fall and holds electronic equipment. It needs "anchored" to the brick wall. ASAP please, before the shelf falls.		
114161	7/13/01	Go see Trailer 25. Replace or cut off long screw holding mouse pad to keyboard pullout on both workstations and reposition keyboard pullout on workstation. Est. is 2 men / 2 hrs.		
114189	7/13/01	Install gov't furnished door and new stops. Remove old door and stops and prep prime and paint new door, stops and jams.		
114193	7/13/01	need to put rubber padding inside of round cylinder at bottom of H-46 vertical shaft dolly thank-you		
114214	7/13/01	Attention Ground Support: Overhaul and repair rolling parts cart to include corrosion control. EIN: 65923 045107 (EDR reads in history)		
114283	7/16/01	replace rubber on feet of 4 step workstand thank-you very much		
114312	7/16/01	Replace ceiling tiles that have been damaged by leaks. Leak has been repaired. Remove and dispose of old tiles.		
114375	7/17/01	Need two latches installed on two test stands so they can be locked up. Contact POC ASAP. Shop to supply locks.		
114433	7/18/01	Repair ergonomic computer stand. Section that holds the monitor is broken. It needs a pin replaced so it will fit in the channel that holds the monitor in place.		
114449	7/18/01	Replace the wood on a parts cart. Cart is located at the welding shop for work.		
114451	7/18/01	Need to replace the wood as necessary on a 402 rotor cart located at the carpenter shop.		
114453	7/18/01	Retract mechanism on double doors in the annex is off the door hinges. Needs immediate attention		
114457	7/18/01	Need to replace the wood as necessary on a pushcart located at the carpenter shop.		
114494	7/18/01	Ceiling tiles falling down in the phone room, Mezzanine B.		
114507	7/18/01	Need to replace the rubber pads on a 4-step workstand located at the carpenter shop.		
114513	7/18/01	Need to replace the rubber on an AV8 stabalator dolly located at the carpenter shop.		
114521	7/18/01	Cut 9 small pieces of plastic per instruction		

Ticket Number	Date	Description of Problem	
114623	7/19/01	Door next to beam CC13 has a broken return actuator. There is a piece of metal hanging in the doorframe that could cause a head laceration. Please remove damaged pieces until new parts are installed.	
114686	7/19/01	Handle of drawer on new bookcase has broken & needs to be repaired so that the drawer can be opened	
114786	7/20/01	Need to replace the wood on a parts cart located at the carpenter shop	
114900	7/23/01	Need approx. 6 more tank covers; 1/4 in. plywood w/center handle 35-1/2" x 46-1/2" w/pipe cutouts. Thanks	
114968	7/24/01	Need to replace wood on parts cart. Cart is currently located at the welding shop for casters.	
114969	7/24/01	Replace the wood on a pushcart located at the carpenter shop.	
115071	7/24/01	The automatic closure cylinder has broken loose on the entrance door to the Precision Measurement Center (PMC)	
115164	7/25/01	The main entrance door to the safety office has a broken retractor arm. Also, the door is rusting and needs to get another coat of paint. Repair or replace the broken door closer, treat the rust and paint the door.	
115167	7/25/01	Install keyboard tray	
115275	7/26/01	Repair bad ceiling tiles in the QA mezzanine Bldg 137	
115474	7/30/01	Mount fire extinguisher per instructions. Mezzanine B	
115621	7/31/01	Remove 2 each self-contained breathing apparatus (SCBA) containers mounted on bldg 133 outside walls & deliver to the safety office. Located to the right of the front main entrance & on Taylor drive side by the high voltage fence & rollup door.	
115688	8/1/01	Need door replaced. The door is split at the top hinge where the screws went in.	
115741	8/1/01	Need to replace the wooden shelves (3 ea) on a parts cart located at the carpenter shop.	
115751	8/1/01	Replace door closer on door to hatch in RCA room. Pneumatic door closer.	
115761	8/1/01	Need to install wood on parts cart located at the carpenter shop. Number 000011	
115763	8/1/01	Cart needs handle reattached to wooden box.	
115764	8/1/01	Cart needs repair and wheels	
115769	8/1/01	Wood cart needs repair	
115770	8/1/01	Wood cart needs repair	
115805	8/2/01	Reinstall doorway and door in enclosure on mezzanine for security as per site visit.	
115808	8/2/01	Need a piece of 1/4 or 3/8-inch plywood and a matching piece of Plexiglas cut. Dimensions will be 42 inches by 30 inches. I will pick up when called, thank you.	
115826	8/2/01	need to replace & paint wood on 402 comp pushcart thank-you very much	
115830	8/2/01	Tow Motor ran into table, instead of getting off tow motor and asking us to move stuff he forced his way through and one of the legs is almost completely off the incoming table. Not safe to use as is. Need repaired AS SOON AS POSSIBLE	
115850	8/2/01	Replace, upright supports for wagon end piece. Relocate sideboard locks.	

Technical Exhibit 3.36, Page 25 of 30 Revised: 04/03/03, 11:01 AM

Ticket Number	Date	Description of Problem			
115867	8/2/01	A section of the mezzanine has been torn off at the elevator stop. This leaves a gap between elevator and mezzanine. The detached section is on the mezzanine.			
115872	8/2/01	need to replace wooden shelves on parts cart. Thank-you very much			
115873	8/2/01	need to replace & paint wood on compressor pushcart. Thank-you sir			
115916	8/3/01	Need to make 2 ea shelves for parts cart number 000009			
115923	8/3/01	Repair engine blade cart as necessary (pe-c87-f402)			
115924	8/3/01	Back of bookshelves are coming off. These bookshelves were provided by NADEP. 4 for repair, large in size.			
115927	8/3/01	Small wood box needs repair			
115971	8/3/01	Hang a bulletin board in his office.			
115978	8/3/01	X-ray film processor was removed from wall leaving a hole 36x52. Hole needs to be repaired			
115979	8/3/01	X-ray film processor removed from control room leaving a hole in the tile on the floor 36x36. Hole needs to be repaired			
116162	8/7/01	Need to replace the wood on a CH46 blade dolly. Dolly is located at the welding shop to have metal repair done. When complete needs to go to paint			
116165	8/7/01	Non-skid on stairway in clean room is breaking off. Repair ASAP.			
116198	8/7/01	Cut 5 pieces of Plexiglas per instructions.			
116296	8/8/01	Ceiling tile and stripping falling down in the ladies room. Replace the ceiling panels and dispose of the old ones.			
116350	8/9/01	Need to install inserts in shop blade carts as necessary.			
116377	8/9/01	Door has swollen due to the humidity, adjust keeper so door will latch.			
116431	8/9/01	Replace damaged ceiling tiles caused by leaks. DO NOT DO THIS JOB UNTIL THE LEAK HAS BEEN FIXED ON TICKET #116427.			
116482	8/10/01	Relocate fire extinguisher as per fire marshal			
116586	8/11/01	Repair hinge on door to back room.			
116589	8/11/01	Repair doors on all of the doors in the penthouses on the roof of 133, poc 2nd shift. ASAP please			
116645	8/13/01	The weather strip is torn off half of the door. It is creating a hazard entering the door at the side entrance Roll-up door.			
116929	8/15/01	Manufacture shipping container for compressor bullgear.			
117014	8/16/01	Install latch on door of fiberglass repair room next to supervisor's office for shop 95441.			
117035	8/16/01	Need rubber padding on blade seating stand in H3 & 53D leading edge rinse tank. Blades are being damaged, need ASAP.			
117038	8/16/01	Adjust/snug up cross bracing on shelter. Replace safety mirror attached to the west side of shelter.			
117041	8/16/01	Replace damaged front door as required. Replace damaged flooring as required. Seal/flash windows as required. Install drain trap on HVAC unit condensate drain. Perform request as per site visit.			
117042	8/16/01	1 piece of 3/4" plywood, 22 3/8" x 60", and 2 pieces of 1"x2" at 60" long.			
117173	8/17/01	Frame print per instructions			

Ticket Number	Date	Description of Problem		
117202	8/17/01	Repair desk.		
117334	8/20/01	Replace plywood as necessary		
117340	8/20/01	Need bulletin board installed on wall (need screws drilled into brick wall.) Located old union office by the machine shop at bldg 137		
117348	8/20/01	There are several tables in the shop that need the felt replaced.		
117401	8/21/01	Construct two walls to make a new office. Install a door w/light 1 3/4" thk with lever handle hardware. Install moldings to match remove old shelves and prep, prime, and patch walls to match.		
117439	8/21/01	Replace the lid on a 53 fuel cell box		
117515	8/21/01	Ceiling tiles in the H-46 air vehicles area need replaced. Leak was fixed, but ceiling tiles not replaced yet.		
117552	8/22/01	Install 3/4" plywood shelves on pushcart.		
117553	8/22/01	Re-install wheels with new bolts, nuts, flat washers, and lock washers on pushcart.		
117564	8/22/01	Please make modifications to the new CO's office.		
117602	8/22/01	Change caster on pushcart. Cart located in the welding shop.		
117603	8/22/01	Small wood cart needs new wheels		
117604	8/22/01	Small wood cart needs new wheels		
117605	8/22/01	Fasteners have fallen out of door closure in Men's restroom door.		
117606	8/22/01	Small wood cart needs wheel		
117623	8/22/01	Install a holder on the wall to hold my phone so I have access to it.		
117654	8/22/01	Request someone inspect/adjust automatic door closers on all 4 front doors and 1 back door for bldg 488. Doors not closing properly still a security concern.		
117698	8/23/01	Need to replace bad wood on CH-46 wrap a round workstand located at the carpenter shop. Someone almost fell through.		
117746	8/23/01	Door is mommicked. Coming off hinge. Will not close properly. Extra arm strength required.		
117821	8/24/01	Re-install wheels on pushcart.		
117830	8/24/01	install new plywood doors and plywood back on cart.		
117904	8/27/01	Need to replace the wood on 4 ea push parts carts as necessary. Carts are located at the carpenter shop.		
117914	8/27/01	Repair molding on outgoing counter. Shop 94203 Poc: Sta 2		
117959	8/27/01	Repair broken (wooden) gate in the AVDLR cage.		
118030	8/28/01	Install doorstops on doors entering into p507. Two sets of double doors.		
118067	8/28/01	Need to put rubber on the shelves of a pushcart to protect the parts when moved. Cart located at the carpenter shop.		
118088	8/28/01	Need to make 6ea Tank cradle ends as per sample located at the carpenter shop.		
118090	8/28/01	Modify keyboard/mouse set up.		

Ticket Number	Date	Description of Problem	
118196	8/29/01	Repair/replace ceiling grid and tiles as per site visit. Remove and dispose of trash as required and as per site visit.	
118198	8/29/01	Modify x-ray developer room in building 4275 to accommodate new processor. See for the hand wave on exactly what needs to be done.	
118280	8/30/01	Hang a whiteboard in PMA Bldg 1665. Est. is 2 men / 2 hrs.	
118284	8/30/01	Remove rubber mats and put no-skid on deck in front of large stripper tank!	
118323	8/30/01	Please install Plexiglas and retirement certificates on plaques as per instruction.	
118328	8/30/01	Door closer on personal door has come apart and won't close door.	
118330	8/30/01	need to replace wood on parts cart thank-you very much pa #516360	
118339	8/30/01	Please repair F-402 pushcarts as per instruction.	
118346	8/30/01	need to replace wood on mobile parts storage dolly pa #000034 thank-you very much	
118359	8/30/01	need to replace rubber padding on bottom of feet of 3 step w/s thank-you very much	
118360	8/30/01	Install 3/4" A/C plywood on parts cart.	
118364	8/30/01	need to replace padding on bottom of feet of 3 step w/s. P/a #65923m19211	
118365	8/30/01	Install 3/4" A/C Plywood on every other shelf. Starting with the bottom one.	
118367	8/30/01	Install 3/4" plywood in pushcart starting from the bottom and work every other one. CIN 658895173850	
118372	8/30/01	Need to replace padding on bottom of feet of 3-step w/s. Thank-you very muc	
118428	8/31/01	Hydraulic door retractor is broken. Door is located in bldg 137 going into H53 pmt office.	
118489	8/31/01	Need to replace the rubber on 4ea H46 vertical shaft dollies located at the carpenter shop. No pa numbers	
118544	9/4/01	Fire extinguisher bracket is broken at I-beam D-9	
118604	9/4/01	Need to replace the rubber on a compressor stand located at the carpenter shop.	
118616	9/4/01	Please fabricate one piece of plywood (3/8 inch) and one piece of Plexiglas, both having the dimensions of 25 X 34 inches. Will be picked up thank you.	
118618	9/4/01	Need to replace the wood as necessary on a pushcart located at the carpenter shop.	
118619	9/4/01	Need to replace the wood on a parts cart located at the carpenter shop. Number 000083	
118649	9/5/01	Ceiling tiles near bathroom entrances need to be replaced	
118654	9/5/01	Swing door on the counter in the lobby is broken. The brackets seem to be "sprung".	
118681	9/5/01	New door needs to be trimmed in size to fit door facing.	
118682	9/5/01	Need to replace the bolts in the support piece on a f-4 radome dolly located at the carpenter shop.	
118752	9/5/01	Need a doorstop installed on vestibule door opposite production control in main aisle.	
118799	9/6/01	Install keyboard pullout. Est. is 2 men / 2 hrs.	
118802	9/6/01	Desk drawer needs repair.	

Technical Exhibit 3.36, Page 28 of 30 Revised: 04/03/03, 11:01 AM

Ticket Number	Date	Description of Problem		
118822	9/6/01	Install doors on a wooden cabinet		
118871	9/6/01	Replace 17 ceiling tiles in new annex upstairs, B133. Est. is \$4 per tile for 2 men / 4 hrs.		
118897	9/7/01	Relocate two workbenches to facilitate new enclosed cleaning and painting work area Need to be wired for 400 cyc. And 28 vdc. See attached.		
118898	9/7/01	Manufacture shadow box.		
118918	9/7/01	Need traps to cover transmissions for CH-46 shop		
119053	9/10/01	Please put a rubber mat over the top of a tank at the end of the NDI line next to the pneumatics area The existing top is metal and is damaging parts.		
119095	9/10/01	Put back ceiling tile taken out from front office area, Bldg 137.		
119128	9/10/01	Relocate a hanging wall unit and hang a board. Thanks		
119181	9/11/01	Closer broken on an outside door to a climate controlled workspace.		
119192	9/11/01	Need to replace the wood on a parts cart located at the carpenter shop. #000082		
119194	9/11/01	Need to replace the wood on a parts cart located at the carpenter shop. 65923045248		
119195	9/11/01	Need to replace the wood on a parts cart located at the carpenter shop. #000081		
119197	9/11/01	Need to replace the wood on a parts cart located at the carpenter shop. 65923045290		
119198	9/11/01	Need to replace the wood on a parts cart located at the carpenter shop. #000084		
119199	9/11/01	Need to replace the wood on a parts cart located at the carpenter shop. #000053		
119242	9/13/01	Door is binding on frame, will not close properly		
119278	9/13/01	Need 1 sheet of Plexiglas cut 24" x 136" and one cut 33" X 24"		
119387	9/14/01	Cut slots in 2 X 4 as per instructions		
119466	9/17/01	Ours part washer it not heating up we need it look at ASAP work stoppage thank you.		
119469	9/17/01	Large storage cabinet has broken drawer. This drawer needs to be fixed ASAP due to fact it is used for securing employment certifications and other confidential employee info. POC 960 Sec		
119475	9/17/01	have maintenance personnel come by to order air hoses for the paint shop.		
119484	9/17/01	Please repair F-402 pushcart as needed.		
119521	9/17/01	Replace wheels/casters on H-53 Fuel Cell Box.		
119530	9/17/01	The D-1 Door does not close properly. We have been notified by security that the D-1 Door will need to be locked 24 hours a day. If you don't pull or push the door it will not close. Door closer must be adjusted.		
119554	9/17/01	There are several tables in the shop that need the felt replaced.		
119556	9/17/01	Desk drawer needs repair.		
119604	9/18/01	Need a bulletin board hung on the outside of the break room		

Ticket Number	Date	Description of Problem	
119612	9/18/01	Large storage cabinet has broken drawer. This drawer needs to be fixed ASAP due to fact it is used for securing employment certifications and other confidential employee info. POC 960 Sec.	
119654	9/18/01	Install pull out tray for computer keyboard. POC for details	
119718	9/19/01	Hydraulic power and lube problems.	
119740	9/19/01	Adjust left hand door of interior doors so it will close right	
119744	9/19/01	Storage door pulled apart needs repair in f-402 area	
119790	9/19/01	Code 6.2.960 has requested handles be installed on all drawers in the large storage cabinet located on Mezzanine A, adjacent the main staircase leading to Mezzanine A.	
119833	9/20/01	Install corkboard on wall outside office. THANK YOU AND GOOD JOB!	
119966	9/21/01	Need a wooden, corner unit built - for new office. Thanks	
119996	9/21/01	Please repair/replace double wood doors going into the thermal image inspection room (underneath mezzanine j) fabricated door is coming apart and needs repair.	
120010	9/21/01	Provide 2 sheets plywood at least 5/8" thick-for a hot job.	
120020	9/21/01	Need to cut 12ea Pieces of plywood at 41 1/2" x 75" x 5/8" thick.	
120114	9/24/01	Upper door stop broken door will not close	
120138	9/24/01	Need to have (20) pieces of 1/4 inch. plywood cut by 12 x 12 inches square.	
120199	9/24/01	Modify opening and install door as per site visit.	
120283	9/25/01	Door leading to the back room will not close.	
120357	9/26/01	Move the cage wall from approx. 15' back over to wall. Put 3/8" plywood on outside perimeter wall of cage from floor to top of plate. Rework the cage door to the customer's preference.	
120445	9/26/01	Back door to eatery will not lock, said it is not the lock, the wall needs to be stabilized, door re-hung so it will close properly. secured the door for today, but this will need fixed by 2:00p.m. On 9/27/2001.	
120497	9/27/01	Repair door closure to bldg 4173.	
120505	9/27/01	Install doorstops on entrance doors to shop 94404 and 94406.	
120536	9/27/01	Repair or replace door opener at ATB	
120565	9/27/01	Install new middle drawers on new modular workstations, Trailer 25. Send to 655.	

TE 3.36 - Woodwork and Carpentry Repair Work Orders

TE 3.37 - Maintenance Painting Work Orders

Government provides data on historical workload in this technical exhibit. This data is raw and represents actual communication among customers, maintenance planners, and artisans. The data is as it appears in the maintenance management system except for removal of personal information, inappropriate language, and acronyms expanded as practicable. Each set of data includes a ticket number, ticket date, and a problem description. The tickets approximate the work required during the base one-year period.

The work orders numbers in this technical exhibit may not match exactly the workload forecast in Section C-7. There are two reasons. First, customers occasionally submit more than one requirement for a single problem indicating the recorded workload over represents the work performed. Second, artisans perform a substantial fraction of their work on verbal orders or on their own initiative indicating the recorded workload under represents work performed. However, the net result approximates actual work required.

We audited by sampling the workload in each technical exhibit. We also sought subject matter expert advice on the amount of over- and under-reporting in each area. The result is our estimate of the amount of over- and under-reporting of each workload set. Thus, to get the forecast values in C-7 for the workload in this Technical Exhibit, we first decreased the number of tickets by 2.9 percent to adjust for over-reported requirements. The then increased the number of tickets by 20 percent to adjust for under reported tickets.

Ticket No	Date Created	Problem Type	Description
89633	10/2/00	Exterior	Paint the wall facing bldg 133 of the C-Scan bldg.
89635	10/2/00	Paint	Hydro-stop the flashing on the hangar windows above mezzanine F.
89808	10/3/00	Interior	Prep and paint switch gear equipment room
89820	10/3/00	Exterior	Prep and paint guard shacks at gates 3 and 4
89868	10/4/00	Exterior	Clean, prep and paint waste drums as per requestor
89873	10/4/00	Exterior	Clean, prep and paint "no parking" area as per attached request and above requestor
89903	10/4/00	Interior	Touch up hallway outside double steel door, bldg 137. Need ASAP
89931	10/4/00	Exterior	Need to paint safety lines on the flightline around the C130 jacks and jack tester. This is a safety issue and has been approved. Needs to be a priority. Contact for further information.
90018	10/5/00	Exterior	Blast & paint hook block

Technical Exhibit 3.37, Page 1 of 22 Revised: 04/03/03, 11:02 AM

Ticket No	Date Created	Problem Type	Description
90021	10/5/00	Interior	Paint trim in panel room
90040	10/5/00	Paint	Re-caulk windows in top of building 4034. This will require a lift.
90044	10/5/00	Paint	Prep, prime, and paint bollards around strip barn and the associated hydrants.
90045	10/5/00	Exterior	Paint hydrants, bollards, and rails for General's visit on Thursday.
90090	10/6/00	Exterior	Paint newly installed door and frame in the strip barn.
90104	10/6/00	Exterior	Paint the mule carts that require painting; several are being repaired and need to be painted.
90204	10/10/00	Exterior	Need to blast, prime, and paint. Check welds and repair as necessary. (hub dolly 020817 and 7-step 047192)
90206	10/10/00	Exterior	Need to blast, prime, and paint 3 ea vertical prop dollies. Weld any cracks and replace casters as necessary. 244484 and 244460.
90209	10/10/00	Exterior	Need to blast, prime, and paint 3 ea tank cradles. Weld any cracks as necessary and replace casters as necessary. 061612, m18869.
90225	10/10/00	Exterior	Need to blast, prime, and paint 2 ea tail blade dollies and 1 C130 cradle. 510859, 510520. Weld any cracks and replace casters as necessary.
90226	10/10/00	Exterior	Need to blast, prime, and paint 3 ea horizontal prop carts. Weld any cracks and replace wooden inserts like the ones that were done last time. (the slots need to be deeper) 513240, 513244.
90432	10/11/00	Exterior	Paint mule carts as required to return to service.
90435	10/11/00	Interior	Paint floor around pump motors and paint sprinkler lines in electrical room
90438	10/11/00	Interior	Prep and paint mezzanine in tubing area adjacent to heat treat
90480	10/12/00	Exterior	Prep and paint fire wall between sections a and b
90482	10/12/00	Interior	Paint base around air handlers and paint doors in pump room
90485	10/12/00	Exterior	Prep and paint exterior north side of wall separating NADEP part of building from the station side
90502	10/12/00	Exterior	Prep prime paint walls in the drawing files new area including the hallway. Patch all holes.
90632	10/13/00	Interior	Touch up paint wall in office-small area need ASAP
90646	10/13/00	Exterior	Paint newly modified carts in 657 compound.
90647	10/13/00	Interior	Prep and paint compressor frames and doors
90651	10/13/00	Exterior	Prep and paint wall in kitting area
90665	10/13/00	Exterior	Need to blast, prime, paint, and replace casters on prop stands. Remove old rubber but do not replace. 7 ea
90666	10/13/00	Exterior	Need to blast, prime, paint, and replace casters on 6ea Prop stands. Remove rubber but do not replace.
90667	10/13/00	Exterior	Need to blast, prime, paint, replace wood and casters as necessary on 5 ea Prop stands. Replace rubber.
90668	10/13/00	Exterior	Need to blast, prime, and paint a H53 rotor head dolly. Replace casters as necessary.

Technical Exhibit 3.37, Page 2 of 22 Revised: 04/03/03, 11:02 AM

Ticket No	Date Created	Problem Type	Description
90669	10/13/00	Exterior	Need to blast, prime, and paint 3ea H53 transmission assy. Stands.
90672	10/13/00	Interior	Office was being remodeled and painters patched over existing phone jack. Phone cannot be plugged in now.
90856	10/17/00	Interior	Repair and paint the wall by my desk. The sprinkler and telephone people made a mess.
90869	10/17/00	Interior	Provide cleaning of mold & mildew on walls floor and ceiling in the triple tach room of shop 94101. Paint as necessary. Safety discrepancy
90919	10/17/00	Exterior	Prep, prime, and paint eaves around buildings shown on walk around.
90955	10/17/00	Interior	Prep, prime, and paint walls in compressor room.
90958	10/17/00	Exterior	Prep, prime, and paint weld mounts on new trailers in the GSE compound.
91131	10/19/00	Exterior	Clean & paint autoclavesoutside of them
91310	10/20/00	Exterior	Prep, prime, and paint walls in compressor room also remove and dispose of ceiling debris.
91311	10/20/00	Exterior	Paint new structure on blade carts.
91313	10/20/00	Exterior	Prep, prime, and paint bollards, sprinklers and hydrants.
91475	10/23/00	Exterior	Need to paint the steps on aluminum workstand with non-skid. Stand is located at the bldg 84 paint shop.
91494	10/23/00	Exterior	Need to blast, prime, paint, and replace casters on J79 twin pack stand and on ladder workstand. 046911
91495	10/23/00	Exterior	Need to blast, prime, and paint H53 rotor headstand.
91496	10/23/00	Exterior	Need to blast, prime, paint, and replace the wooden inserts and rubber on 5 ea prop carts. 513223, 513224, 513225, 020776, 513183.
91499	10/23/00	Exterior	Need to blast, prime, paint, and replace casters on J79 twin pack stand and on ladder workstand. 046911
91608	10/24/00	Interior	Paint safety lines in aisle way as per requestor
91610	10/24/00	Exterior	Paint and label debris containers as per requestor
91665	10/25/00	Interior	Paint break area on mezzanine in small components shop
91679	10/25/00	Exterior	The ready service lockers (RSL's) located outside bldg 188 require their respective bldg numbers painted on them. Ref NAVSEA OP 5 VOL 1 paragraph 8-8.1
91735	10/25/00	Interior	Paint inner office in screening
91799	10/26/00	Interior	Paint inner office in screening
91800	10/26/00	Interior	Paint inter office in screening
91820	10/26/00	Exterior	Need to blast, prime, and paint H53 transmission dolly.
91822	10/26/00	Exterior	Need to blast, prime, paint, and replace the casters as necessary on a double eaps dolly, H53 stabalator dolly, and an H53 tank cradle.
91825	10/26/00	Exterior	Need to blast, prime, paint, and replace the casters as necessary on 3 ea Prop carts.

Ticket No	Date Created	Problem Type	Description
91826	10/26/00	Exterior	Need to blast, prime, paint, and replace casters as necessary on a H53 shaft dolly, prop cart, and a single prop stand.
91885	10/26/00	Exterior	Prep, prime, and paint new woodwork on carts to be used by transportation.
91965	10/27/00	Exterior	Paint smoking area as required
92147	10/30/00	Interior	Prep and paint steam room as per requestor
92149	10/30/00	Interior	Prep, prime, and paint ceiling area in compressor room
92151	10/30/00	Interior	Prep and paint mezzanine in small surfaces shop
92152	10/30/00	Exterior	Paint new cart for transportation.
92154	10/30/00	Interior	Prep and paint handrails and stairs
92305	10/31/00	Exterior	Need to blast, prime, paint, and replace the casters as necessary on 3 ea prop carts.
92416	11/1/00	Interior	Repair ceiling and replace panels painting as required
92418	11/1/00	Interior	Prep, prime, and paint steam water and electrical lines in steam equipment room
92437	11/1/00	Exterior	Prep, prime, and paint hoppers located in scrap yard
92438	11/1/00	Interior	Prep, prime as required, and paint floor adjacent to mezzanine stairs adjacent to the clean room
92566	11/2/00	Paint	Prep prime, and paint hydrants and pipe bollards around building 4498.
92569	11/2/00	Interior	Prep, prime, and paint walls and trim in 188 (transportation office)
92623	11/3/00	Interior	Sand prime, and paint shelves under mezzanine adjacent to engine line
92624	11/3/00	Interior	Prep, prime, and paint floor in steam room
92625	11/3/00	Exterior	Prep, prime, and paint shelter located on the back side of building
92630	11/3/00	Exterior	Prep, prime, and paint personnel doors, roll up doors and equipment mounts
92632	11/3/00	Exterior	Prep, prime, and paint steam building adjacent to building 1798
92785	11/6/00	Exterior	Prep, prime, and paint hydrants, bollards, and pull stations and remove trash and debris.
92813	11/6/00	Exterior	Repaint parking lot # 12 as per attached.
92814	11/6/00	Exterior	Repaint parking lot by building 143 per attached.
92884	11/7/00	Interior	Prep and paint shelving in blade storage area
92958	11/7/00	Interior	Prep, prime, and paint steel framework and pipes.
93043	11/8/00	Paint	Prep, prime, and paint mule carts.
93051	11/8/00	Interior	Prep and paint ceiling over condensate pumps in equipment room
93103	11/8/00	Exterior	Need to paint and stencil H53 blade dolly
93104	11/8/00	Exterior	Need to paint and stencil H53 blade dolly
93105	11/8/00	Exterior	Need to paint and stencil H53 blade dolly

Technical Exhibit 3.37, Page 4 of 22 Revised: 04/03/03, 11:02 AM

Ticket No	Date Created	Problem Type	Description
93106	11/8/00	Exterior	Need to paint and stencil H53 blade dolly
93111	11/8/00	Interior	Space in front of the door of the TTU-209 room below mezzanine F needs to be repainted yellow, paint is badly worn. This area is a no standing area safety problem exists.
93202	11/9/00	Interior	Mezzanine extending over Transmission Shop 6.2.96119 has flaking paint on the underside which can fall in the balance machines thus causing FOD. This mezzanine underside needs to be cleaned, primed, and painted.
93211	11/9/00	Interior	Mezzanine extending over Transmission Shop 6.2.96119 has flaking paint on the underside which can fall in the balance machines thus causing FOD. This mezzanine underside needs to be cleaned, primed, and painted.
93228	11/9/00	Exterior	Prep and paint block walls around transformers/electrical equipment next to building
93232	11/9/00	Exterior	Prep and paint fire escape
93257	11/9/00	Exterior	Prep, prime, and paint cart hitches/frame as required
93340	11/13/00	Interior	Prep and paint hallway between 93000 and old safety office area
93605	11/15/00	Interior	Prep, prime, and paint walls in equipment room
93608	11/15/00	Interior	Paint ceiling in room adjacent to the tool room of building 133
93609	11/15/00	Exterior	Prep, prime, and paint hoppers
93610	11/15/00	Exterior	Prep, prime, and paint scrap material containers as required
93611	11/15/00	Interior	Prep, prime as required and paint downstairs offices in building
93617	11/15/00	Interior	Paint hallways with contemporary white wainscot
93635	11/15/00	Paint	Water running in around window during rain.
93684	11/16/00	Exterior	Prep, prime, and paint new repairs and modifications to mule carts.
93705	11/16/00	Exterior	Paint and stencil can lid/per woody west
93754	11/16/00	Interior	Prep and paint stairwell and stairs in building office area
93925	11/20/00	Exterior	Numbered parking spaces behind 4033 and 163 were relocated and renumbered. Old lines are more visible than new - new numbers more visible than old. This leads to errors in parking. Parking lines need to be repainted and old lines blocked out better.
94219	11/22/00	Interior	Prep and paint electrical equipment as per site visit with poc
94225	11/22/00	Interior	Prep, prime, and paint wall next to tool room aisle in mach shop
94229	11/22/00	Interior	Clean, prep and paint wall/trim adjacent to eatery
94252	11/22/00	Interior	Paint floor in equipment room upstairs bldg 4188
94312	11/24/00	Exterior	Clean and repair siding using degreaser as required. Paint exterior doors/trim
94313	11/24/00	Exterior	Prep and paint building siding as required
94319	11/24/00	Interior	Prep and paint floor in small components shop area

Technical Exhibit 3.37, Page 5 of 22 Revised: 04/03/03, 11:02 AM

Ticket No	Date Created	Problem Type	Description
94320	11/24/00	Interior	Prep, prime, and paint new concrete floor under mezzanine in front of components blast shop area
94341	11/25/00	Interior	Please paint the air conditioner frame on the roof and in the equipment room. Also paint the equipment room. (new air conditioner is installed.) Thanks
94489	11/28/00	Interior	Prep, prime, and paint floor in askars kitting area
94493	11/28/00	Interior	Paint safety lane as per requestor
94504	11/28/00	Interior	Prep, prime, and paint floor
94544	11/28/00	Interior	Prep and paint tool room lock up area
94546	11/28/00	Exterior	Prep and paint cart modifications
94646	11/29/00	Interior	Please paint the air conditioner frame on the roof and in the equipment room. Also paint the equipment room. (new air conditioner is installed.) Thanks
94679	11/29/00	Interior	Graffiti on walls of men's room, mezzanine f, bldg 137 Could you please paint over it
94819	11/30/00	Paint	Put two strips of molding and caulk. Old doorway behind desk. Send to WCRO1.
94885	12/1/00	Exterior	Prep and paint building
94890	12/1/00	Interior	Prep and paint equipment in equipment room according to color coding schedule provided
94894	12/1/00	Interior	Paint wainscoting on mezzanine adjacent to 93000 division office
94898	12/1/00	Interior	Repair, prep and paint piping and hangers in comp room
94910	12/1/00	Exterior	Prep, prime, and paint parts carts.
95016	12/4/00	Exterior	Need to paint non-skid on 11 ea aluminum workstands after they leave the carpenter shop.
95208	12/5/00	Exterior	Paint various frames that are pitted and rusted.
95211	12/5/00	Exterior	Prep, prime, and paint hydrants, 3 bollards, a rail, and several vents safety yellow.
95213	12/5/00	Exterior	Prep, prime, and paint bollards, fire hydrants, and sprinkler valves. This is a safety issue. Needs to be visible for fire dept.
95225	12/5/00	Interior	Clean mold and repaint hallway and conference room. Mold due to excessive a/c output.
95229	12/5/00	Exterior	Prep, prime, and paint mule carts.
95274	12/6/00	Interior	Prep and paint utility supply/condensate/etc. Lines as per provided color scheme
95405	12/7/00	Interior	Prep prime paint Front side office wall, steps, and railing
95409	12/7/00	Interior	Backboard that were installed (task #98701) need to be painted white to match the other shop backboard in shop 94405
95532	12/7/00	Exterior	Prep, prime, and paint steel structure on roof that holds a/c units.
95585	12/8/00	Exterior	Need to paint non-skid on 11 ea aluminum workstands after they leave the carpenter shop.
95786	12/11/00	Exterior	Prep and paint lines in parking lot no. 12

Ticket No	Date Created	Problem Type	Description
95791	12/11/00	Exterior	Prep and paint scrap material hoppers to be delivered to the contractor per requestor
95847	12/12/00	Exterior	Paint and install landing gear stump. ASAP!
95882	12/12/00	Exterior	Clean & paint autoclaves outside of them
95918	12/12/00	Interior	Prep and paint walls and utility boxes on sw side of machine shop
95920	12/12/00	Interior	Prep and paint (color coded) utility lines in equipment room
96006	12/13/00	Interior	Prep and paint utility lines and equipment
96011	12/13/00	Interior	Prep and paint walls in equipment room next to high hazard area
96079	12/14/00	Interior	Prep and paint pipes where old wall was removed, demo built in tables/cabinets and dispose of debris
96093	12/14/00	Interior	Prep and paint metal work in NE end of old blast shop
96158	12/14/00	Interior	Prep and paint exterior wall of electric shop
96193	12/15/00	Exterior	Paint new wood in compressor room to match.
96256	12/15/00	Interior	Please paint the 93552 office (inside). See for more info. Thanks
96370	12/18/00	Exterior	Paint warning signs on all 3 overhead roll up doors as well as the pavement areas before the doors. (see shop supervisor for paint scheme) please place on priority list.
96372	12/18/00	Exterior	Paint walls in rooms that got damaged during move.
96415	12/18/00	Exterior	Paint office areas vacated by MOD Team, bldg 137
96473	12/19/00	Exterior	Repair, frame, prep, prime, and paint.
96474	12/19/00	Exterior	Prep, prime, and paint gray tool carts.
96481	12/19/00	Exterior	Paint warning signs on all 3 overhead roll up doors as well as the pavement areas before the doors. (see shop supervisor for paint scheme) please place on priority list.
96560	12/20/00	Interior	Prep, patch, paint walls in rear of machine shop
96762	12/21/00	Interior	Prep and paint SE end of blast room
96925	12/27/00	Interior	Request several holes in office wall be caulked and touched up
97008	12/28/00	Exterior	Clean & paint autoclavesoutside of them
97106	12/29/00	Interior	Paint walls in shop area adjacent to the small components paint shop
97107	12/29/00	Interior	Paint electrical equipment to match NADEP color coding
97108	12/29/00	Interior	Prep and paint aisle ways in prop shop
97110	12/29/00	Interior	Prep and paint pmb blast booth
97307	1/3/01	Exterior	Need to paint non-skid on the floor part of 3ea floorboard dollies
97492	1/4/01	Paint	Prep, prime, and paint the following carts. S/n: 061710, 063596, 06590
97494	1/4/01	Paint	Prep, primed, and paint gray tool carts: s/n 02799 & 02797. Repaired and painted yellow cart #513317

Ticket No	Date Created	Problem Type	Description
97578	1/5/01	Interior	Prep and paint SE wall in old blast shop
97589	1/5/01	Interior	Prep and paint wainscoting on walls in C130 prop area
97749	1/8/01	Interior	Prep and paint NW wall of room adjacent to the new blast room
97807	1/8/01	Exterior	Need to paint and stencil H53 blade dolly located at the 84 paint shop
97808	1/8/01	Exterior	Need to paint and stencil a H53 blade dolly located at the 84 paint shop
97809	1/8/01	Exterior	Need to paint and stencil a H53 blade dolly located at the 84 paint shop
97810	1/8/01	Exterior	Need to paint and stencil a H53 blade dolly located at the 84 paint shop
97843	1/8/01	Interior	Prep and paint wall in machine shop as per on site visit
97845	1/8/01	Interior	Prep and paint walls in old comp room
98083	1/10/01	Paint	Re finish table top (the table top is in the carpentry shop)
98140	1/11/01	Interior	Prep and paint electrical equipment in room located behind tool room as per on site visit
98142	1/11/01	Interior	Prep and paint water chiller equipment and lines as per on site visit
98186	1/11/01	Interior	Prep and paint electrical equipment and lines in high hazard equipment room
98224	1/11/01	Exterior	NEED WORK BENCH STAND PAINTED page when done
98225	1/11/01	Exterior	Need to paint H-46 blade dolly. Dolly is located in GSE compound thank-you and have a nice day
98227	1/11/01	Exterior	Need to paint H-46 blade dolly. Dolly is located in GSE compound thank-you and have a nice day
98228	1/11/01	Exterior	Need to paint H-46 blade dolly. Dolly is located in GSE compound, thank-you and have a nice day
98229	1/11/01	Exterior	Need to paint H-46 blade dolly. Dolly is located in GSE compound, thank-you and have a nice day
98230	1/11/01	Exterior	Need to paint H-46 blade dolly. Dolly is located in GSE compound, thank-you and have a nice day
98233	1/11/01	Exterior	Need to paint H-46 blade dolly. Dolly is located in GSE compound, thank-you and have a nice day
98340	1/12/01	Interior	Prep and paint walls in compressor room
98343	1/12/01	Interior	Prep and paint inspection area floor as per on site visit
98346	1/12/01	Interior	Prep and paint floor at NE end of old blast shop
98348	1/12/01	Interior	Repair, prep and paint doors, and NE wall as required per site visit
98417	1/16/01	Interior	Prep and paint shop floor as per site visit
98424	1/16/01	Interior	Prep and paint floor in the furnace area of shop
98430	1/16/01	Interior	Repair, prep and paint foyer, trim, and doors as per on site visit
98485	1/16/01	Interior	Prep and paint walls in switchgear room

Technical Exhibit 3.37, Page 8 of 22 Revised: 04/03/03, 11:02 AM

Ticket No	Date Created	Problem Type	Description
98488	1/16/01	Interior	Prep and paint roll up door and foyer leading to high hazardous area
98513	1/16/01	Interior	Clean, remove adhesives from floor and paint as required
98600	1/17/01	Paint	Blast, prime, and paint 5 ea non-imrl stands P/N: 65889411382, 65889511933, 65889669405, and one with no number.
98602	1/17/01	Paint	Blast, prime, and paint a large transmission dolly and hand sand and paint a small hydraulics cart. Transmission dolly # 65889514371 and hydraulics cart number 65923052097.
98607	1/17/01	Paint	Blast, prep, prime, and paint 5 ea non-imrl GSE gear p/n: 65923076067, 65889675675, 652923037075, and 00000098568, and one with no number.
98608	1/17/01	Exterior	Prep, prime, and paint the frame per attached.
98663	1/17/01	Exterior	Paint bollards by new RPZ by scrap yard. Prep, prime, and paint yellow.
98665	1/17/01	Exterior	Prep, prime, and paint hydrants and bollards at the corner of the material storage compound and the plating shop.
98690	. 1/17/01	Interior	Prep and paint break room as required
98692	1/17/01	Interior	Prep and paint floor surrounding prop clean room area
98778	1/18/01	Interior	Prep and paint C-130 propulsion repair area floor
98931	1/19/01	Exterior	Paint 3 large El boxes
98981	1/19/01	Interior	Prep and paint storage room per on site visit
98983	1/19/01	Interior	Prep and paint storage room
99030	1/22/01	Interior	There is paint residue buildup on the floor of the paint spray booth in building 4032. Buildup of this residue is a fire hazard and could result in flash fire. Violation of 29 CFR 1910.107.
99087	1/22/01	Exterior	Paint compressor room, pneumatics areas, bldg 137
99103	1/22/01	Paint	Repaint floor in area of shop 536, bldg 133
99228	1/23/01	Exterior	Please paint H-53 fuel cell boxes as per instruction.
99256	1/23/01	Exterior	Paint 3 each H-46 Fuel Cell Boxes as per instructions.
99344	1/24/01	Exterior	Prep and paint dumpsters as per requestor
99347	1/24/01	Interior	Prep and paint floor adjacent to kitting and retrieval system
99348	1/24/01	Interior	Patch holes, prep, and paint compressor room walls
99381	1/24/01	Paint	Need to replace the padding on a e2/p3 prop dolly.
99465	1/25/01	Interior	Prep roll up doors and NE end walls of components testing shop
99468	1/25/01	Interior	Prep and paint walls and columns in shop area under old safety office
99471	1/25/01	Interior	Prep, prime, and paint ceiling
99502	1/25/01	Exterior	Need to paint non-skid on 1 step workstand.
99508	1/25/01	Interior	Paint red strips on floor by Vault #2 back door and letter "DO NOT BLOCK".

Ticket No	Date Created	Problem Type	Description
99608	1/26/01	Interior	Paint floor area by Electrical Panel to identify as Safety Hazard. Navosh Deficiency Notice 321-00
99630	1/26/01	Exterior	Install rubber pads and paint non-skid on 3 each work stands as per instruction.
99674	1/26/01	Exterior	Please paint two trip hazards located in X-Ray with yellow and black stripes.
99696	1/27/01	Interior	Requesting a 3-foot wide exit path painted on the floor for fire exit.
99879	1/30/01	Paint	Remove metal from wall behind guard's desk and patch wall. Prep, prime, and paint wall to match. Replace as necessary the hinge bushings in all lobby doors.
99908	1/30/01	Exterior	Storage room door needs scraping, prepping, priming, and painting per AIS.
99916	1/30/01	Exterior	Scrape/paint the rusting metal ventilation housings on the roof. (7 units) AIS
99922	1/30/01	Interior	Prep and paint shop floor as per on site visit
99924	1/30/01	Interior	Prep and paint floor at rear of comp room as per on site visit
99966	1/30/01	Paint	Need non-skid put down on wood ramps in front of trailer's 33 & 34.
100032	1/31/01	Interior	Prep and paint C-130 prop blast booth area
100033	1/31/01	Interior	Prep and paint air lines
100034	1/31/01	Interior	Provide paint for shop floor
100041	1/31/01	Paint	Install anti-skid flooring in vestibule and on guard desk area
100049	1/31/01	Paint	Windows are leaking water in Computer Room, bldg 137. Hydrostop wall from windows to top of metal flashing on mezzanine G, bldg 137. Urgent!!!
100051	1/31/01	Exterior	Please paint pipes for heater duct holders. Ref ticket 97148
100127	2/1/01	Exterior	Paint lines and stencil no parking per attached.
100131	2/1/01	Interior	Mezzanine g paint office for 21300 POC for details
100288	2/2/01	Interior	Paint floor in pre espended bin room
100322	2/2/01	Exterior	Need to put some non-skid on 3-step workstand. Thank-you very much
100425	2/5/01	Interior	Mezzanine G paint office
100428	2/5/01	Exterior	Need to put non-skid on one step workstand located at paint shop at bldg 84. thank-you very much
100440	2/5/01	Interior	Please paint platform as per instructions
100445	2/5/01	Interior	Paint/Seal clamp rack in carpenter shop.
100548	2/6/01	Interior	Prep and paint walls in test stand area of building as per requestor
100553	2/6/01	Paint	Remove paint from floor
100555	2/6/01	Interior	Prep and paint floor in compressor area
100629	2/6/01	Paint	Clean, prep, patch walls in back room of Graphic Arts, bldg 137. Remove equipment/other items as required.

Technical Exhibit 3.37, Page 10 of 22 Revised: 04/03/03, 11:02 AM

Ticket No	Date Created	Problem Type	Description
100643	2/6/01	Interior	Paint other side of extension mezzanine 19-3 - 19-2
100646	2/6/01	Interior	Please spray and seal sick leave plaques as requested by the CO.
100703	2/7/01	Interior	Prep and paint floor in PEB room in building 137
100776	2/7/01	Exterior	Paint personnel door "A" street side of bldg 133
100930	2/8/01	Interior	Patch, prep and paint wall in rear of high pressure test room
100932	2/8/01	Interior	Prep and paint walls and columns as per site visit
100937	2/8/01	Interior	Prep and paint wall near autoclave
100940	2/8/01	Interior	Prep and paint tool storage room walls
100941	2/8/01	Interior	Prep and paint area as per site visit
100944	2/8/01	Exterior	Paint floor in the hall of the 930 sbu; Floor paint gray; Steps paint yellow; Rail paint black; Paint the unpainted wall to match the others
100953	2/8/01	Interior	Prep and paint office of above requestor
101014	2/9/01	Exterior	Paint personnel door "A" street side of bldg 133
101033	2/9/01	Interior	Patch and paint pedestrian aisle in machine shop area Call to schedule. Request this be done on Sunday or long weekend to preclude complaints about the odor of the paint. Thank You.
101046	2/9/01	Exterior	Clean and paint frames back in the can area and around the compound and NADEP.
101055	2/9/01	Exterior	Need to paint C-130 rudder/elevator white. thank-you very
101142	2/12/01	Interior	Prep and paint office and storage area as per site visit
101145	2/12/01	Interior	Prep and paint doors and stairs in lobby
101155	2/12/01	Exterior	Prep and paint dumpsters as per requestor
101160	2/12/01	Interior	Prep and paint roll-up door and wall in high hazard area
101163	2/12/01	Interior	Prep and paint utility lines in building
101206	2/12/01	Exterior	T-58 compressor rotor boxes need painted 20 each.
101207	2/12/01	Exterior	T-64 compressor rotor boxes need painted 10 each
101210	2/12/01	Exterior	Lpc boxes need painted 10 each
101334	2/13/01	Exterior	Paint lines around Eye Wash Station.
101425	2/14/01	Interior	Prep and paint pipes, brackets and other items as per site visit
101429	2/14/01	Interior	Prep and paint aisle way as per site visit and requestor
101434	2/14/01	Interior	Thoroughly clean and paint upper sump for test cell #3.
101435	2/14/01	Exterior	Please clean and paint rusted area outside of bldg
101480	2/14/01	Paint	Need to have someone caulk or putty the corners on the inside of the toyoda FH80B machine. The machine leaks when you wash it down, especially when washing in the corners.

Ticket No	Date Created	Problem Type	Description
101491	2/14/01	Interior	Paint one each box (10"x10"x10") bright yellow and stencil as per instructions already provided.
101518	2/14/01	Paint	Need to have someone caulk or putty the corners on the inside of the toyoda FH80B machine. The machine leaks when you wash it down, especially when washing in the corners.
101579	2/15/01	Interior	Paint back room of Graphic arts where walls have been patched
101580	2/15/01	Exterior	Need to paint CH46 blade dolly located in the dog pound storage area
101582	2/15/01	Exterior	Need to paint CH46 blade dolly located in the dog pound storage area
101583	2/15/01	Exterior	Need to paint a CH46 blade dolly located in the dog pound storage area
101584	2/15/01	Exterior	Need to paint a CH46 blade dolly located in the dog pound storage area
101585	2/15/01	Exterior	Need to paint a CH46 blade dolly located in the dog pound storage area
101629	2/15/01	Paint	Please return all tenant floor paints and tints to Hazmat storage bldg 4247
101693	2/16/01	Interior	Prep and paint walls and trim in room next to pneumatic test cells as per on site visit
101695	2/16/01	Interior	Prep and paint roll up door and trim work as per on site visit
101700	2/16/01	Interior	Prep and paint walls adjacent to the hydraulic test stands located in the south corner of building 133
101718	2/16/01	Exterior	Need to paint and stencil H46 blade dolly after the welding shop has completed the work on it.
101795	2/20/01	Interior	Prep and paint SE wall and trim in high hazard
101853	2/20/01	Exterior	Paint short wall in carpenter shop before new shelving is installed
102015	2/21/01	Exterior	Paint with anti-skid paint approx 20 helicopter work stands.
102028	2/21/01	Exterior	Pre, prime, and paint all the roof ladders on the building safety yellow.
102036	2/21/01	Exterior	Need to prime, and paint 60 ea pipes for the heaters. Pipes are located at the paint shop.
102038	2/21/01	Exterior	Paint parts for pre heater
102084	2/22/01	Interior	Prep and paint equipment and piping as per requestor/site visit
102085	2/22/01	Interior	Prep and paint general maintenance area
102129	2/22/01	Interior	Please paint wall inside of carpenter shop.
102255	2/23/01	Interior	Paint floor in carpenter shop where racks was removed
102759	3/1/01	Interior	Men's head stalls need to have graffiti panted over men's head m-25
102817	3/1/01	Interior	Need a piece of wood painted black
102833	3/1/01	Paint	Small ding in wall outside Patch/paint as necessary
102932	3/2/01	Interior	Prep and paint walls in engine prep room
102937	3/2/01	Interior	Clean, prep and paint machinery as per requestor and on-site discussion

Technical Exhibit 3.37, Page 12 of 22 Revised: 04/03/03, 11:02 AM

Ticket No	Date Created	Problem Type	Description
103158	3/6/01	Interior	Prep and paint additional piping/equipment
103160	3/6/01	Interior	Prep and paint floor on SE side of aisle in small components paint shop
103163	3/6/01	Interior	Prep, prime, and paint walls in electrical room
103361	3/7/01	Interior	Floor paint/sealant is worn and/or flaking off floor in work area Cannot maintain exposed concrete as required. Scrape flaking paint, approximately 120 SF, clean area and paint to match the existing color as close as possible.
103385	3/8/01	Interior	Please paint rack as per instruction.
103397	3/8/01	Interior	Clean and degrease ceiling, walls and equipment in building 3402
103400	3/8/01	Interior	The 4.3 Department office was totally painted Jan 01. The Dept Head rearranged his office and took down his white board to put on the other side of his room and found they had not painted under the white board. Request painting that portion of wall.
103401	3/8/01	Interior	Clean, degrease, prime, paint and label piping as per on site visit
103402	3/8/01	Interior	Clean, scrape, prep, prime, and paint wall in equipment room as per on site visit
103517	3/9/01	Paint	Repair 1-inch hole in wall left from removal of computer cable.
103540	3/9/01	Exterior	Need to paint H-46 blade dolly,
103544	3/9/01	Exterior	Need to have H53 blade dolly located at the carpenter shop sent for blast and then painted.
103546	3/9/01	Exterior	Need to have H53 blade dolly located at the carpenter shop sent for blast and then painted.
103608	3/9/01	Exterior	Repaint aircraft alignment line on floor going into av8 hush house (yellow)
103638	3/12/01	Interior	Clean, degrease equipment, remove debris, primer as required and paint as per on site visit
103641	3/12/01	Interior	Prep, prime, and paint ceiling in building as per site visit
103717	3/12/01	Exterior	Blast and paint C130 dolly
103968	3/14/01	Interior	Painting piece of wood black all sides
104059	3/14/01	Exterior	Need to paint and stencil H53 blade dolly located at the paint shop
104060	3/14/01	Exterior	Need to paint and stencil H53 blade dolly located at the paint shop.
104153	3/15/01	Interior	Paint 3 rails yellow
104467	3/20/01	Interior	Paint pans for air compressors
104490	3/20/01	Interior	Repair, clean/prep walls and wainscot in electrical room
104492	3/20/01	Interior	Clean and remove debris, prep, prime, and paint walls, seal bare areas where paint is peeling, wainscot as per NAVAVNDEPOT paint scheme in storage locker area
104516	3/20/01	Paint	Take down approx dozen wall-mounted bookcases from "old 52500 office" in B133, paint them, and mount in mezzanine A, B133. Color and mounting location 6.3.616

Ticket No	Date Created	Problem Type	Description
104737	3/22/01	Paint	Need sheets lam.
104743	3/22/01	Exterior	Need to paint and stencil H53 blade dolly located at the paint shop.
104777	3/23/01	Interior	Repair wall and paint to match existing next door office
104778	3/23/01	Interior	Prep, prime, and paint equipment per site visit
105053	3/27/01	Paint	Need to putty around screw pull to desk drawer.
105060	3/27/01	Interior	Paint day gate for vault #1 black before installation by 655SM
105158	3/28/01	Exterior	Need to paint H53 ramp/door dolly white. Dolly is located at the paint shop.
105301	3/29/01	Exterior	Need to blast, prime, and paint CH53 blade dolly. Pa number 65923046814
105420	3/30/01	Interior	Repair doors, prep prime, and paint doors and trim as per site visit
105689	4/3/01	Interior	Paint grates with black high temp paint. Paint if within monetary limit.
105710	4/3/01	Interior	File cabinet needs to be painted
105718	4/3/01	Exterior	Portable vacuum pumps need painting
105725	4/3/01	Interior	File cabinet needs to be painted
105782	4/4/01	Interior	Touch up any holes in the walls and paint the "new" office in Westbrooke. He will occupy office starting Friday, Apr 4. This is an additional request to Task 112526, JON 7F5ZJD0
105831	4/4/01	Exterior	Paint reserved below parking spaces 24/24 and 24/25
105845	4/4/01	Interior	Prep, prime, and paint floor as per site visit
105919	4/5/01	Interior	Request to have paneling on secretary's desk sanded and stained or painted.
105921	4/5/01	Exterior	Request to have all access steps and ramps on both trailers painted with non-skid paint.
105930	4/5/01	Paint	Paint booth over spray accumulation needs to be cleaned up and steps taken to prevent further accumulation. Fire inspection write up. Ref: NFPA 33 8.2
105962	4/5/01	Exterior	Paint Street Lines for AV8 Movement
106352	4/10/01	Paint	Reattach loose seams on wallpaper in front lobby and hallway to conference room. Request it be completed before the IG/ISO Command Reception. Needs completed by 7 May 01.
106353	4/10/01	Interior	Repair holes in sheetrock wall and water damage and paint damage area in front lobby. Request this be completed before the IG/ISO Command Reception. Needs completed by 7 May 01.
106573	4/12/01	Paint	Refinish conference table top in Bldg 143.
106680	4/13/01	Exterior	Stencil/paint equipment room door & area outside door as per instruction.
106812	4/16/01	Paint	Patch small section of corridor wall next to new conf room
106898	4/17/01	Interior	Paint corridor from double steel entry doors front office to main production aisle

Technical Exhibit 3.37, Page 14 of 22 Revised: 04/03/03, 11:02 AM

Ticket No	Date Created	Problem Type	Description
106967	4/18/01	Paint	Fix hole in wall, outside of office
107013	4/18/01	Exterior	Prep, prime, and paint floor with 2-coats of (2-part) Polyurethane floor paint. Prep, prime, and paint walls and doors with 2 coats wall paint. Existing floor is extremely oil prep accordingly.
107077	4/19/01	Exterior	Replace cradle ends and cart sides as required, prep, prime, and paint carts numbered 4057, 4069, 04059 and 06039
107199	4/20/01	Exterior	Expedite - paint compass rose located on flightline across from bldg 245 this weekend. Contact for info.
107259	4/23/01	Paint	Patch a hole and paint to match the existing in the drywall on mezzanine A bldg 133, damage caused by furniture movers.
107336	4/23/01	Interior	Patch the holes in the walls and paint walls one coat.
107683	4/26/01	Interior	Patch the holes in the newly remodeled Security Office where the surface mounted fire alarm was removed and run inside the wall. Paint to match existing.
107802	4/27/01	Interior	Paint 3 red poles, without fire extinguishers, white. See prior to painting
107935	4/30/01	Interior	Repaint 3'x 8' workbench in fabrivision scanner room in component, manufacturing, weld and repair shop 6.2.93653. Room is directly across aisle from east side doors to eatery.
108064	5/1/01	Interior	Prime and paint 4 each compressor housings for CENTAC #1. Send to 65500.
108172	5/2/01	Paint	Repair wood, canvas, and brackets as required. Sandblast and paint as required transportation carts numbered 62251, 76400, 60360 and 061715 per site visit
108240	5/3/01	Interior	Prepare and paint Masonite in the old office and hallway.
108330	5/4/01	Interior	Work platforms and inside surface of machine guard need to be cleaned and painted with nonskid paint. Small area, probably less than 6 sq feet total, need worked done on Friday to allow drying time over weekend
108338	5/4/01	Paint	Clean and wax NEAC sign at bldg 4225
108567	5/7/01	Interior	Paint areas in main aisles in the transverse hanger area that were recently repaired
108639	5/8/01	Exterior	Paint brackets
108699	5/8/01	Interior	Paint 1 each 2 drawer security container gray
108780	5/9/01	Interior	Floor in plastic media blasting hanger needs painting. Needs to be non-skid surface, you can use plastic media for the non-skid. Do not use steel shot or sand. Thank you very much.
108787	5/9/01	Exterior	Paint lines as per task 109249
108827	5/10/01	Painting	Paint on floor peeling, cannot keep clean. Test area was painted on 05/05-06/01. The rest of the floor in work area needs to be painted.
108843	5/10/01	Interior	Paint scale with rust kill and then with white paint
109031	5/11/01	Interior	Prep and paint interior office walls to match newer offices located in same general area
109070	5/11/01	Interior	Prep and paint ceiling in shop area as per on site visit

Ticket No	Date Created	Problem	Description
	Created	Туре	Clean film/regidue from eiding and prop prime point on per on
109174	5/14/01	Interior	Clean film/residue from siding and prep, prime, paint as per on site visit and as required
109266	5/15/01	Exterior	Need to have Red and Yellow Boundary lines around Blast Storage Area re-painted and stenciled. Please call for exact details.
109277	5/15/01	Interior	Scrape and prime rust on the hanger doors on A Street side of hanger. Paint doors up 6 ft inside & out.
109281	5/15/01	Exterior	Ref ticket 109016, paint push cart to match GSE equipment
109757	5/21/01	Paint	Please repair holes in walls and ceiling in rear mechanical room to prevent the avenue for fire.
109793	5/21/01	Interior	The bathroom stalls in men's room of 53 hanger needs to be repainted because of the racial slurs on walls of stalls.
109861	5/22/01	Interior	Paint all inside walls of office B159. Must be done by COB Friday, May 25
109933	5/22/01	Paint	Repair and paint holes in wall of Code 6.2.960 Main SBU Office, Mezzanine A, bldg 133. Paint to match existing color scheme.
110209	5/24/01	Interior	Need the floor by the coffee mess and the sink painted. This will allow the area to be kept cleaner. View area and submit quote.
110254	5/25/01	Exterior	Paint power unit outside electric shop. See for location
110288	5/25/01	Interior	Prep and paint electrical room as per site visit
110384	5/29/01	Exterior	Clean, prime, paint lower section of Hanger 1 doors, runway side, bldg
110422	5/29/01	Exterior	Scrape and prom and paint pipes on cooling tower also paint hoist rail .
110525	5/30/01	Interior	Procure locker and paint white. Label all sides GOLD PLATE"/
110551	5/30/01	Exterior	Prepare, prime, and paint the stands for cooling towers 1 & 2 in front of hanger three bldg 137
110578	5/31/01	Interior	Need safety cage painted after it is installed around ladder leading to mezzanine.
110580	5/31/01	Interior	Paint cart after modification by welding shop, per instructions
110598	5/31/01	Interior	Paint rack per instructions
110904	6/4/01	Exterior	Prep, prime and paint sawdust hopper located behind the carpenter shop.
110915	6/4/01	Exterior	Prep, prime, paint platform dumpster adjacent to bldg 4224
111131	6/6/01	Exterior	Need the aircraft grounding stud indicator pads painted these are black and yellow circles around the grounding points.
111140	6/6/01	Exterior	Scrape, treat rust, prime, and paint two coats safety yellow. Roof access ladder bldg 133. See for location and details.
111187	6/6/01	Interior	Prep, prime, and paint electrical equipment in the comp. Room at the rear of building per site visit.
111189	6/6/01	Interior	Prep, prime, and paint structural steel as per site visit
111226	6/7/01	Interior	Paint mural as per customer and site visit.
111305	6/7/01	Interior	Patch and paint an area in the front hall bldg 137
111317	6/7/01	Exterior	Paint sump pump, per instructions

Technical Exhibit 3.37, Page 16 of 22 Revised: 04/03/03, 11:02 AM

Ticket No	Date Created	Problem Type	Description
111427	6/8/01	Interior	Clean, prep, prime as required and paint ceiling in shop as per required site visit.
111428	6/8/01	Interior	Walls in office need painting. The have not been painted in alot of years, and are nasty, have stuff running down them and look unhealthy. Office is located by the entrance of the machine shop bldg 137 (old union office)
111532	6/11/01	Interior	Paint all four walls (3 are vinyl covered) of office next to Legal Conference Room, mezzanine B, Bldg 137.
111553	6/11/01	Exterior	Prepare, prime, and paint the metal columns to the left of cooling towers 1 & 2 in front of hanger 3
111640	6/12/01	Interior	Prep walls, prime, and paint as per the required site visit the walls and columns in storage area
111650	6/12/01	Paint	Prep and coat exterior wall of berm with chemical resistant coating to provide liquid tight seal. Remove and dispose of debris as required.
111697	6/12/01	Exterior	Paint sump pump per instructions
111771	6/13/01	Interior	Prep, prime, and paint walls in newly remodeled compressor room as per site visit. Requires wall repair. Clean and dispose of all debris.
111832	6/13/01	Interior	Paint a fluorescent centerline in the AV-8 Hush House.
111842	6/13/01	Exterior	Need to paint (5) five each e-2/p-3 prop dollies. Pa #075276, 075277, 074702, 513247, and 074700. Also have to have a ticket made to go to p&p for blasting. Thank-you very much
111895	6/14/01	Interior	Repaint capacity rating on bridge for hoist 295 to 6,000 lbs instead of 12,000.
111917	6/14/01	Exterior	Brush some non-skid onto aluminum deck plate at end of handicap ramp on the smoking shelter off the south corner of #83.
112331	6/19/01	Interior	Touch up aisle way. Floor paint in machine shop outside eatery, 137
112374	6/20/01	Interior	Paint the inside of tub compressor room floors white. Scrape the loose covering off the insulation on the walls and ceilings. Repair one piece of insulation in the ceiling.
112407	6/20/01	Exterior	Prepare, prime, and paint outside Bldg 422. Customer service
112421	6/20/01	Interior	Prep, prime as required and paint walls in conference room. Repair, prep, refinish, relocate bulletin board according to requestor and as per site visit.
112578	6/22/01	Paint	Repair, clean and prep floor in comp room as per site visit
112580	6/22/01	Paint	Repair various holes in concrete floor, clean, prep and seal floor in storage area as per site visit
112586	6/22/01	Interior	Clean, prep, prime, and paint structural steel as per site visit
112661	6/25/01	Interior	Floor by the coffee mess was painted over the weekend (6/23-6/24) this was on ticket number 110209. We have a problem, the paint is peeling off the floor. Please have this re-done. Thanks
112692	6/25/01	Interior	Prep and paint CMM room as per site visit
112788	6/26/01	Paint	Line boxes with foam and stencil

Ticket No	Date Created	Problem Type	Description
112931	6/27/01	Exterior	Need to blast and paint (2) two each H-53 blade dollies and (1) one H-46 blade dolly. Need work order from p&p to blast all (3) blade dollies. After blasting return for painting.
113158	6/29/01	Exterior	Paint compressor stand per instructions. Work stoppage, yellow paint
113188	6/29/01	Interior	Anti-slip tape on stairs is starting to peel up. Trip hazard
113204	6/29/01	Interior	Paint middle aisle ways red in bldg 133
113335	7/2/01	Paint	Silicone the front exterior of 4225 to prevent further water damage during wind driven rainstorms.
113340	7/2/01	Interior	Clean, prep, prime, and paint various items in shop area as per site visit
113415	7/3/01	Interior	Paint the pipes NADEP'S color scheme making sure no paint gets on the newly painted floor. Cover insulation with a sealant.
113499	7/5/01	Exterior	Staircase on east side of Rotary Wing QA office has peeling paint that has sharp edges. Also where the paint has peeled, the railing is very rusted causing rust to be left on hands whenever using that staircase.
113508	7/5/01	Interior	Clean, prep, prime, and paint floor as per site visit
113709	7/9/01	Paint	Windows on right side of building down above the small rollup door and exit above work area leaks when it rains hard and blows was done once but it still leaks would be nice if it could be fix right this time before any equipment gets damaged
113716	7/9/01	Exterior	Please paint 8" wide florescent orange line around the entire scrap yard with the words OFF LIMITS AUTHORIZED PERSONEL ONLY! At intervals along the line. Also, manufacture enough signs to post on all sides of the compound and on columns next to JP-5 tank.
113762	7/10/01	Interior	Paint walls in Plant Account area, Mezzanine Bldg 4224
113776	7/10/01	Exterior	Need to paint the wooden pieces after the carpenter shop makes them for the H53 double eaps dollies.
113782	7/10/01	Exterior	Prepare and paint exterior trim bldg.422
113848	7/10/01	Interior	Paint line on floor for QEC Area
113916	7/11/01	Exterior	Need to paint and stencil 6 ea H53 double eaps dollies. Also need to have work order written to have the same dollies blasted before paint.
113983	7/11/01	Interior	Clean, prep, prime, and paint wainscot in storage area as per site visit.
113984	7/11/01	Interior	Clean, prep, prime, and paint floor as per site visit. Repair floor as required.
114054	7/12/01	Interior	Prep, prime, and paint wall next to offices and under mezzanine. As per site visit.
114096	7/12/01	Exterior	Paint tire rack located at paint shop that was manufactured on ticket # 113395
114344	7/17/01	Interior	Prep, prime, and paint floor in storage room as per site visit
114350	7/17/01	Interior	Prep, prime, and paint wall in GSE area of building as per site visit.
114351	7/17/01	Paint	Repair wall and paint to match as per site visit.

Ticket No	Date Created	Problem Type	Description
114436	7/18/01	Exterior	Need to paint and stencil 6 ea H53 double eaps dollies also need to have work order written to have the same dollies blasted before painting. New Ticket- the old one, #113916, was closed for some reason.
114450	7/18/01	Exterior	Need to paint a parts cart. (white) cart is located at the welding shop for repairs.
114454	7/18/01	Exterior	Need to paint a 402 rotor cart located at the carpenter shop.
114456	7/18/01	Exterior	Need to paint a 402 rotor turbine stand. (white) stand is at the welding shop for repairs.
114458	7/18/01	Exterior	Need to paint pushcart (white) located at the carpenter shop.
114510	7/18/01	Exterior	Need to paint non-skid on a 4-step workstand. Stand is at the carpenter shop for repairs.
114511	7/18/01	Exterior	Need to paint a 3-step workstand with non-skid. Stand is located at the paint shop
114524	7/18/01	Interior	Hoist 119 in heat treat room needs disconnect box painted orange.
114837	7/23/01	Exterior	Need to paint a wooden parts rack that is currently located at the carpenter shop for repairs. Paint white and stencil 96000 parts rack.
114892	7/23/01	Interior	Clean and degrease walls, prep and repair walls as required, paint walls in canteen as per site visit
115003	7/24/01	Exterior	Need to paint and stencil a J-79 compressor-housing stand. (white) located at the paint shop bldg 84
115027	7/24/01	Paint	Request window repair office. Water leaks around the window when it rains. It was leaking badly during yesterdays storm.
115074	7/24/01	Interior	Paint door
115124	7/25/01	Exterior	Paint parts rack, ref ticket 114542
115125	7/25/01	Exterior	Paint access door, ref ticket114499
115160	7/25/01	Exterior	Need to paint and stencil 2 ea H53 tail rotor blade dollies as required.
115164	7/25/01	Interior	The main entrance door to the safety office has a broken retractor arm. Also, the door is rusting and needs to get another coat of paint. Repair or replace the broken door closer, treat the rust and paint the door.
115254	7/26/01	Exterior	Request work order for 655 Paint Shop, to paint rollaway toolbox (GSE White). Box is to be delivered to paint shop by 6.3.611. POC for pickup upon completion
115500	7/30/01	Interior	Sand, paint, and assemble and set up metal storage racks. Relocate from Connor Warehouse to new building behind Bldg 4032. Use JON 7F5ZBIT
115528	7/30/01	Interior	Scrap ceiling, walls and floor of old varsol still- room. Prep prime, and paint walls ceiling and doors.
115611	7/31/01	Exterior	Paint door in test cell.
115702	8/1/01	Interior	Paint floor of the H-46 Hangar on Sunday, August 12, 2001.
115801	8/2/01	Interior	Clean, prep, repair, prime, and prep floor as per site visit. Remove and dispose of debris as required.
115941	8/3/01	Exterior	Part of the front of the AV-8 Hush House needs to be repainted. See for details.

Technical Exhibit 3.37, Page 19 of 22 Revised: 04/03/03, 11:02 AM

Ticket No	Date Created	Problem Type	Description
115967	8/3/01	Exterior	Sandblast 2 fan blades.
115973	8/3/01	Interior	Clean, prep, prime, and paint floor in south end of new storage area
116164	8/7/01	Exterior	Need to make work order to have h46 blade dolly blasted when welding shop is complete and then have al paint and stencil.
116417	8/9/01	Interior	We need you all to steam clean floor walk platform to prevent slipping & falling. Seal concrete to prevent chemical saturation.
116435	8/9/01	Interior	Paint aisle ways in building 4225 per instruction. Work needs to be completed before the upcoming Admiral's visit.
116437	8/9/01	Interior	Clean ceiling on top of office beside mezzanine G. Prep, prime, and paint floor area at the base of the stairs at mezzanine G. Lean walls and paint wainscot on steps to mezzanine G. Replace ceiling tiles in Men's head on mezzanine G.
116606	8/13/01	Interior	Prep, prime, and paint the following: 3 a/c ducts, touch up 3 columns, paint approx. 40' of wall white with wainscot; paint the noses of the stair treads leading up to mezzanine F. Paint the wainscot as required up the mezzanine F stairs.
116634	8/13/01	Exterior	Need to paint and stencil a 12-step workstand that will be located at the paint shop when the welding shop completes its work. No pa #
116707	8/13/01	Interior	The men's bathroom located above the eatery has vulgar writing on the walls that is particularly offensive to an employee that works in that area Please repaint the walls.
116714	8/13/01	Exterior	Need to paint and stencil a heater located at the paint shop
116723	8/13/01	Exterior	Exterior doors on building 129 ordnance shop rusting. Need to remove decals, scrape/rust removal/paint. Wire brush rusty areas, prime with a rust treatment primer. Paint two coats to match existing. 1set double doors and 1 single door with frames.
116742	8/14/01	Exterior	Due to construction, Repaint - The below listed "RESERVED" parking spaces. 12-18, 13-05, 13-06, 13-07, 13-08, 13-09. Requestor did not identify which parking lot on request.
117039	8/16/01	Interior	Due to Fire Inspection write-up we must have a line painted designating barrier for driving cart inside building. Must have done ASAP. Thanks
117044	8/16/01	Exterior	Need to paint the wheels from 2 ea Heaters
117300	8/20/01	Exterior	Paint inside lobby doors
117442	8/21/01	Paint	Remove paint from spray room floor as per site visit
117473	8/21/01	Exterior	Need "reserved" painted on space 24-26 in parking lot in front of bldg 1665.
117477	8/21/01	Interior	Clean, prep, prime, and paint floor as per site visit.
117609	8/22/01	Paint	Patch hole in interior masonry wall in Magnaflux room and touch up paint afterwards.
117610	8/22/01	Interior	Patch hole in interior sheetrock wall after electrical panel has been removed. Touch up paint wall afterwards. Wall is located in room next to Heat Treat control room in bldg 4225.
117612	8/22/01	Exterior	Repaint 3-foot personnel door by receiving area in bldg 4225. Scrape peeling paint off the floor next to Springfield grinder. This grinder is located in machine shop area

Ticket No	Date Created	Problem Type	Description
117649	8/22/01	Exterior	Repaint letters on the NADEP Taxi parking spaces in front of building 133. There are two spaces.
117672	8/23/01	Exterior	Repair/replace gate section next to Can 1350. Possible cut and weld new gate section and reattach fence fabric.
117844	8/24/01	Paint	Clean, prep and repair floor as per site visit
117897	8/27/01	Exterior	Paint bicycle rack.
117898	8/27/01	Exterior	Need berm area of 4225 outlined with yellow paint and labeled "Danger Hazardous Waste" on 4 sides.
117905	8/27/01	Exterior	Need to paint and stencil 4 ea Push parts carts as necessary. Carts are at the carpenter shop for wood.
118017	8/28/01	Interior	Prep, prime, and paint green floor area from the scale room down to the hangar door and Prep, prime, and paint the starter test cell floor in 94402.
118019	8/28/01	Interior	Clean and paint as necessary the carts that load the GM furnaces in bldg 4255. Item that was part of a walk around.
118070	8/28/01	Interior	Paint the edge of the aisle by rotating electric shop with NADEP approved green paint. Prep, prime, and paint the hallway by the old Pneumatics Hot air test cells green.
118098	8/28/01	Paint	Provide paint sample for CO's office.
118160	8/29/01	Interior	Clean, prep and paint equipment room floor as per site visit.
118197	8/29/01	Interior	Prep, prime, and paint floor in aisle as per site visit. Coordinate paintwork with production effort as required.
118317	8/30/01	Exterior	Need to paint and stencil (2) two each dbl eaps dollies. Thank- you very much
118340	8/30/01	Exterior	Paint all F-402 pushcarts.
118669	9/5/01	Exterior	Need to prime, and paint heater located at the paint area
118729	9/5/01	Paint	Install foam liner and stencil boxes as required by drawing
118772	9/6/01	Exterior	Due to employee safety concern, please mark and paint a walkway on the road behind the safety/qa building. Cars are not giving right of way as people walk across the road to the parking lot # 5
119059	9/10/01	Interior	Prep, prime, and paint inside and outside of supervisor's hooch. Replace floor tile with new and replace ceiling tiles. Reinstall sprinkler inside hooch and connect to sprinkler system.
119080	9/10/01	Exterior	Need to paint (6) six each rims as required. Thank-you very much
119081	9/10/01	Exterior	Need to paint heater as required thank-you very much
119168	9/11/01	Interior	Clean, prep and paint office area in building as per site visit.
119179	9/11/01	Paint	Clean paint booth (scrape inside paint build-up)
119240	9/13/01	Paint	Apply filler to deep holes in floor as required, apply one coat of epoxy mortar surfacer (1/4" thick) as per mfg, apply two coats epoxy mortar sealer as per mfg.
119610	9/18/01	Paint	Provide non-skid floor for office identified on attached sheet.
119620	9/18/01	Exterior	Need to paint heater as required thank-you very much

Industrial Maintenance Services Maintenance Painting Work Orders (continued)

Ticket No	Date Created	Problem Type	Description
119621	9/18/01	Exterior	Need to paint heater as required thank-you very much
119784	9/19/01	Interior	Clean, prep and paint qa area as per site visit. (AIS report; task no. 109014)
119897	9/20/01	Interior	Prepare and paint walls per instruction
119965	9/21/01	Interior	Had a wall unit removed and the wall needs to be painted. Thanks
120235	9/25/01	Exterior	Need to paint (4) four each tires thank-you very much
120240	9/25/01	Interior	Prep, prime, and paint hallway as per site visit. (area adjacent to clean shop.
120241	9/25/01	Interior	Prep, prime, and paint walls as per site visit.
120249	9/25/01	Exterior	Paint engine compressor stand.
120317	9/25/01	Interior	Prep and paint old QE area walls as per site visit.
120354	9/26/01	Exterior	Need to paint heater located at the paint shop
120355	9/26/01	Exterior	Need to paint a heater located at the paint shop
120453	9/26/01	Paint	Epoxy patch holes and indentations identified in the hangar floor prior to the floor paint contract.
120537	9/27/01	Exterior	Paint doors at ATB
120552	9/27/01	Interior	Remove loose interior paint and repaint interior walls of ATB.

TE 3.37 - Maintenance Painting Work Orders